

## Specifications

Soldering Temperature: 250° C, maximum



# Anritsu

## VP Shroud to Coplanar Waveguide Interface VP100BCPW

Figure 1. VP100BCPW Shroud

### 1. Tools and Materials

These tools and materials are needed to install the VP100BCPW Shroud. Equivalent tools may be used if the recommended tools are not available.

Name	Vendor and Model/Part Number
Solder, 80Au/20Sn, washer 3.76 OD, 3.21 ID, 0.13 thick	Indium Co., Indalloy#182 Anritsu 01-503
Solder, 80In/15Pb/5Ag, 0.5 mm dia. wire	Indium Co., Indalloy#2
Cleaning Fluid	Isopropyl Alcohol
Rosin Flux	#1544- HT Kester Co.
Stereo Microscope .07-30X	Bausch & Lomb Stereo Zoom 4

### 2. Machining Dimensions

Machining dimensions for the shroud mounting hole are shown in Figures 2 and 3.

### 3. Installing the Shroud into the Housing

- Flux the shroud and the inner walls of the mounting hole.

#### NOTE

Flux may not be needed if the soldering is done in a reducing atmosphere.


- For a thick-wall housing, place three to four solder washers on the shroud and place the shroud into the housing as shown in Figure 2.
- For a thin-wall housing, place one or two solder washers over the shroud inside the housing as shown in Figure 3.
- Place the housing on 250° C hot plate to flow the solder.
- When the solder starts to melt, push the shroud into the housing so that the shroud flats are aligned with the housing slot.
- Remove the housing from the hot plate keeping the shroud firmly pressed to the housing. Allow the assembly to cool quickly at 3.5° C per second.
- Clean the assembly with alcohol or an equivalent solvent for removing flux.

#### NOTE


Visually verify that there is good solder flow (without any pinholes or gaps) between the outer conductor and the wall of the housing. This will ensure that a hermetic seal is created for the shroud assembly.

### 4. Installing a Substrate Into the Housing

- Cut the 0.5 mm Indium solder wire into 1mm (0.040 inch) long pieces.
- Place 1544 flux and the pre-cut indium solder wire pieces into the ground lip holes.
- Place the preformed solder sheet onto the center trace of the substrate.
- Place the substrate in the housing resting on a carrier (shim), making sure the trace aligns with the connector center pin.
- Place the housing on a 165° C hot plate to flow the solder.
- Remove the housing from the hot plate and allow it to cool at room temperature.
- Remove the carrier (shim).
- Clean the assembly with alcohol to remove the flux and visually inspect all solder joints.



**Figure 2.** VP100BCPW Mounting Hole Dimensions and Assembly Drawing for a Thick Wall Housing



**Figure 3.** VP100BCPW Mounting Hole Dimensions and Assembly Drawing for a Thin Wall Housing