

General Caution

Please use a USB Memory Stick for firmware updates.

If there is a firmware update question, please contact Anritsu service support at <https://www.anritsu.com/test-measurement/contact-us> for further information.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE

Application Package : V4.61

Release Date : Release Apr. 2023

Information below may not apply to every model/option in Product list.

*** NEW FEATURES ***

-> Software - P25/P25p2

[SPH-5060] Adds SINR Measurement to P25p2.

[SPH-5061] Adds SINR Measurement to P25p1.

[SPH-5090] Added a toggle to allow P25P1 and P25P2 customers the ability to measure RSSI using the median of captured subsamples instead of the default which averages the subsamples. This is done to satisfy the requirements of TIA TSB-88.3 Rev F.

-> Software - PIM

[SPH-5105] Resolved 1-port high band spur issue on option 703.

*** IMPROVEMENTS ***

-> Software - OS/Base

[SPH-5111] Adds battery temperature to system status information page.

*** BUG FIXES ***

-> Software - CAA

[SPH-5069] Fixed issue where Marker Table was not being recalled from a measurement file.

[SPH-5095] Fixed issue where Marker Table is not recalled from saved measurement file.

-> Software - NBFM

[SPH-5088] Fixed issue where switching units from dBm to dBuV would cause incorrect output power level.

-> Software - P25/P25p2

[SPH-5024] Fixed issue with P25P2 rising edge alignment in Power Profile Graph.

-> Software - PIM

[SPH-5077] Fixed DTP overlay bug.

[SPH-5098] Fixed issue where 1 port and 2 port calibration was lost on 2 port PIM Master when switching between 1 and 2 port modes.

[SPH-5102] Fixed issue where inaccurate 2-Port DTP results would be reported on 2 port instrument.

[SPH-5104] Blocked 1-Port DTP Overlay Trace recall in 2-Port mode.

-> Software - SPA and Sub-apps

[SPH-4974] Fixed an issue where the PIM Hunting measurement would be turned off after switching mode from SPA PIM Hunting to AM-FM-PM => PIM Analyzer => Spectrum Analyzer.

[SPH-4982] Fixed an issue where the attenuation setting in a saved measurement file was not being recalled correctly.

[SPH-5040] Fixed issue where virtual Keyboard was only partially displayed in IQ Capture mode.

[SPH-5043] Fixed issue with incorrect Occ BW calculation in NBFM mode when dBc method is chosen when signal has single tone modulation.

[SPH-5054] Fixed ADC Over range issue when signal is close to ADC full scale.

-> Software - TETRA

[SPH-5038] Fixed issue where Base station would not stop testing after selecting custom DL pattern.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package : V4.50

Release Date : Release Aug. 2022

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - DMR2

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - NBFM

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - NXDN

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - P25/P25p2

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - PTC

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - TETRA

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

-> Software - dPMR

[SPH-5000] Added signal generator Board ID to the S412E Application Self Test output.

*** IMPROVEMENTS ***

-> Software - CAA

[SPH-5066] Added new Time Delay measurement in the DTF measurement screen (-S33xE -MT821xE -MW82119B). When a marker is used it will display both the DTF information and the Time Delay information. The Time Delay information will also display on the left-hand side and is also available within the marker table.

[SPH-5080] Added 4 additional cables to the standard cable list suite. -ACC014J50 (1/4) -AC012J50 (1/2) -AT078J50 (7/8) -AT114J50 (1 ¼).

-> Software - VNA

[SPH-5080] Added 4 additional cables to the standard cable list suite. -ACC014J50 (1/4) -AC012J50 (1/2) -AT078J50 (7/8) -AT114J50 (1 ¼).

*** BUG FIXES ***

-> Software - DMR2

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - LTE

[SPH-4943] Fixed issue where transient messages will not clear and continue to stack up. One on top of the other while in single sweep.

[SPH-5051] Fixed issue with RSRQ LTE Measurement in MS2720T.

-> Software - NBFM

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - NXDN

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - P25/P25p2

[SPH-4938] Fixed issue where the S412E CW generator FM deviation was not working.

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - PDT

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - PIM

[SPH-4978] Resolved issue where changes to default parameters on the PIM Hunting application are not maintained when leaving mode or when unit is turned off.

-> Software - PTC

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

-> Software - SPA and Sub-apps

[SPH-4938] Fixed issue where the S412E CW generator FM deviation was not working.

-> Software - TETRA

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

[SPH-5082] Fixed issue in the S412E where the fm_1kHz_audio pattern does not work after a custom DL pattern is loaded or deleted.

-> Software - dPMR

[SPH-5046] Fixed S412E Tx Output Level value mismatch after measurement is saved or recalled in Watts.

[SPH-5071] Resolved an issue where S412E Tx Output Level unit in Volts did not recall correctly from a measurement file.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V4.30

Release Date : Quarterly Release April 2021

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - PIM

[SPH-4844] Added Support for MW82119B-0703 option.

*** IMPROVEMENTS ***

-> Software - PIM

[SPH-4510] DTP overlay previously had to be re-applied/measured every time a user switched to another PIM measurement mode (Swept PIM or PIM vs. Time). with this fix the DTP overlay will stay active between PIM measurement modes. This will save the technician time in the field since they will only need a single DTP overlay measurement per antenna.

*** BUG FIXES ***

-> Software - CAA

[SPH-5003] Fixed an issue where the default F1 and F2 frequencies for the MW82119B-0194 model were incorrect.

[SPH-5007] Resolved an issue where setting the option 28 CWSG frequency to 3 decimal places (1 kHz resolution) resulted in the actual CW frequency being rounded to 2 decimal places (10 kHz resolution).

-> Software - SPA and Sub-apps

[SPH-4946] Fixed an issue with functionality of the PIM hunting measurement mode when recalling a setup file.

[SPH-4948] Fixed an issue where the PIM Hunting sweep time was not matching in the status window.

[SPH-5007] Resolved an issue where setting the option 28 CWSG frequency to 3 decimal places (1 kHz resolution) resulted in the actual CW frequency being rounded to 2 decimal places (10 kHz resolution).

-> Software - PIM

[SPH-4674] Fixed an issue where the MW82119B-0700 PIM Master was not remembering non-default F1 and F2 settings.

[SPH-4954] Fixed an issue where user defined F1 and F2 values and calibration were lost going between High band and Low band in the MW82119B-0700 700 MHz PIM Master. The

unit will now remember both the F1 and F2 values and the calibration between High band and Low band.

[SPH-4968] Resolved an issue when using the SCPI command (programming language) to recall the residual PIM value returning the wrong value.

[SPH-4975] Fixed an issue where the residual PIM calibration was not applied to F2 on the MW82119B-0700/-0701 PIM Master models at 20W with the Swept PIM measurement.

[SPH-4977] Fixed an issue in the MW82119B-0700 model that was setting the wrong IM range for Swept PIM measurements after the user makes PIM vs. Time measurements in both Low Band and High Band before making a swept PIM measurement.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V4.20

Release Date : Quarterly Release Jan. 2021

Information below may not apply to every model/option in Product list

*** IMPROVEMENTS ***

-> Software - PIM

[SPH-4510] DTP overlay previously had to be re-applied/measured every time a user switched to another PIM measurement mode (Swept PIM or PIM vs. Time). with this fix the DTP overlay will stay active between PIM measurement modes. This will save the technician time in the field since they will only need a single DTP overlay measurement per antenna.

*** BUG FIXES ***

-> Software - SPA and Sub-apps

[SPH-4939] Fixed an issue in PIM Hunting mode when a user changed the default settings the unit did not remember the last settings.

[SPH-4947] Fixed an issue where the PIM Hunter Menu button would show up in IA mode of operation.

[SPH-4950] Fixed a problem when switching between PIM Analyzer mode (1st generation/legacy PIM Master receiver mode) and PIM Hunting mode in our spectrum analyzers. The sweep in PIM Hunting mode stopped and the left side parameters were not reset.

[SPH-4952] Fixed an issue in PIM Hunting mode. When manually changing the span (normal spectrum analyzer function) and resetting to Zero span or using last span. PIM Hunting mode would not restart. PIM Hunting mode is a Zero Span measurement.

[SPH-4983] Fixed an issue in PIM Hunting mode under certain conditions when switching from PIM Hunting mode to another measurement mode (ie. LTE) the unit would freeze up or reboot.

[SPH-4984] Fixed an issue when in PIM Hunting mode the sweep would slow down if power cycled or switched back and forth between other modes.

-> Software - PIM

[SPH-4674] Fixed an issue where the MW82119B PIM Master was not remembering non-default F1 and F2 settings.

[SPH-4954] Fixed an issue where user defined F1 and F2 values and calibration were lost going between High band and Low band in the MW82119B-0700 700 MHz PIM Master. The unit will now remember both the F1 and F2 values and the calibration between High band and Low band.

[SPH-4958] Fixed an issue in PIM Hunting mode when the 1 KHz RBW was used the trace sweep would stop.

[SPH-4968] Resolved an issue using the SCPI command (programming language) to recall the residual PIM value returned the wrong value.

[SPH-4986] Fixed an issue in PIM Hunting mode when the 1 KHz RBW was used the trace sweep would stop.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T

Application Package: V4.00

Release Date : Quarterly Release Sept. 2020

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - SPA and Sub-apps

[SPH-4917] Resolved an issue where it was not possible to set Zero Span time markers to negative values remotely. This change applies only to Spectrum Analyzer (SPA) modes.

*** IMPROVEMENTS ***

-> Software - SPA and Sub-apps

[SPH-4809] Added .csv file save format for the Cable/Antenna analyzer (CAA) measurements.

*** BUG FIXES ***

-> Software - CAA

[SPH-4935] In response to numerous customer requests, dual trace .dat measurement files will no longer result in 2 individual files saved. Dual trace .dat measurement files saved are fully compatible with Line Sweep Tools (LST). This change affects the Cable/Antenna analyzer (CAA) mode only.

[SPH-4936] Fixed an issue in PIM Hunting mode when the RBW was set at 1 KHz the sweep could freeze.

[SPH-4937] Fixed an issue where the attenuation level was changing based on the Reference Level setting. For the PIM Hunting application this behavior has been changed so that the value stays the same and the default is 0 dB attenuation.

[SPH-4957] Resolved an issue where certain combinations of start/stop frequency and number of data points could result in spikes appearing after calibration.

-> Software - SPA and Sub-apps

[SPH-4949] Fixed an issue where the Spectrum graph in PIM Hunting measurement covered the Center Frequency as well as Span and other annotations in (ms/s) after switching mode from SPA PIM Hunting to AM-FM-PM => PIM Analyzer => Spectrum Analyzer.

-> Software - VNA

[SPH-4830] Resolved an issue where recalling a [Trace + Memory]/2 measurement resulted in the Trace Math function being re-applied.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.90

Release Date : Release May. 2020

Information below may not apply to every model/option in Product list

*** IMPROVEMENTS ***

-> Software - CAA

[SPH-2095] The following cables have been added per customer requests: RLCX-SL 158R, RLCX-SL 114R, RLCX-SL 078R, RLCX-SL012R, RLCX-SL038R, RLCX-SL014R, RLCX-SL012S, RLCX-SL038S, RLCX-SL014S, RLCX-SL012R FPR.

[SPH-4778] CSV file format added to File Save Menu.

-> Software - VNA

[SPH-2095] The following cables have been added per customer requests: RLCX-SL 158R, RLCX-SL 114R, RLCX-SL 078R, RLCX-SL012R, RLCX-SL038R, RLCX-SL014R, RLCX-SL012S, RLCX-SL038S, RLCX-SL014S, RLCX-SL012R FPR.

*** BUG FIXES ***

-> Software - CAA

[SPH-4731] Resolved an issue where sometimes the last point marker value displayed would not match the last point data in the saved measurement.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.80

Release Date : Release Jan. 2020

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - LTE

[SPH-4852] Adding initial support for TD-LTE measurements for S412E.

-> Software - PIM

[SPH-4844] Added Support for MW82119B-0703 option.

-> Software - OS/Base

[SPH-4806] Added support for amplitude blanking capability in S11 and S21 Log Mag graph types only, for models with option 007 installed.

-> Software - SPA and Sub-apps

[SPH-4808] New PIM Hunting mode, used for PIM Hunting applications on rooftops with the PIM Hunting probe or Yagi antennas.

*** BUG FIXES ***

-> Software - P25/P25p2

[SPH-4884] Corrected an error on the Band plan. The frequency and channel numbers for P25 will now be correct.

-> Software - PTC

[SPH-4798] Improved Trigger Timeout message responsiveness.

-> Software - VNA

[SPH-4760] Resolved an issue in VNA Mode where saving a measurement + JPG could result in repeated file confirmation messages.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.70

Release Date : Quarterly Release October 2019

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - CAA

[SPH-4784] Added (Trace + Memory)/2 feature to Trace Memory. Allows users to reduce or eliminate peak-to-peak ripple caused by standing waves when making 1-port cable loss measurements.

*** BUG FIXES ***

-> Software - DMR2

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - NXDN

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - dPMR

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - NBFM

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - TETRA

[SPH-4000] regional language Support for S412E LMR Master is available.

[SPH-4690] Fixed an issue where TETRA Base Station Receiver Sensitivity loading of customer patterns did not operate correctly. Added a softkey to display BCC, MCC, and MNC of loaded BSRS custom patterns.

-> Software - P25/P25p2

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - PTC

[SPH-4000] regional language Support for S412E LMR Master is available.

-> Software - PDT

[SPH-4000] regional language Support for S412E LMR Master is available.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T

Application Package: V3.50

Release Date : Quarterly Release April 2019

Information below may not apply to every model/option in Product list

*** IMPROVEMENTS ***

-> Software - CPRI

[SPH-4627] Added Samsung and Huawei to PIM Aid radio preset selections.

*** BUG FIXES ***

-> Software - SPA and Sub-apps

[SPH-4691] Fixed an issue where field strength measurement settings might not properly apply after power cycle.

-> Software - OS/Base

[SPH-4617] Fixed an issue in S412E where setting the Input Power Warning to ON would prevent the 'available firmware update message' from displaying when appropriate during power-up.

[SPH-4713] Fixed an issue where automatic firmware updates would not execute in S412E under some circumstances.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.40

Release Date : Quarterly Release January 2019

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - CAA

[SPH-4535] Added cal coefficient support for cal kits with 4.3-10 connectors.

-> Software - PTC

[SPH-4442] Added common American Association of Railroads (AAR) frequency standards to our Signal Standards lists, and made them available in PTC mode.

-> Software - SPA and Sub-apps

[SPH-4566] Added dBuW, dBmA, and dBuA units in SPA mode.

-> Software - VNA

[SPH-4535] Added cal coefficient support for cal kits with 4.3-10 connectors.

*** IMPROVEMENTS ***

-> Software - LTE

[SPH-4590] Added Band 71, the new 600 MHz LTE Band to the signal standard list.

*** BUG FIXES ***

-> Software - LTE

[SPH-4597] Fixed an issue where recalled 4x4 MIMO LTE measurement would not properly display the green/grey antenna icons.

-> Software - ISDBT/SFN

[SPH-4687] Corrected the antenna.txt file so that it would behave correctly in ISDB-T mode.

-> Software - VNA

[SPH-4689] Fixed an issue in field mode that unnecessarily limited scale settings in Field Mode VSWR measurements.

-> Software - SPA and Sub-apps

[SPH-3745] Fixed a corner case error with averaging in Interference Analysis Field Strength measurement.

[SPH-4458] Antenna selection list now includes EMI antennas when 'All' is selected.

-> Software - PIM

[SPH-4642] Changed the time/date text layout in the PIM Calibration Due popup.

[SPH-4644] Addressed an issue that could cause an option 600 or 902 instrument to lock up when they are set to high band and perform a calibration via the SCPI command:

CAL:PIM:FULL ON

-> Software - OS/Base

[SPH-4593] Fixed an issue where unit would hang during power-up under certain conditions after recalling a VNA setup from SPA mode.

-> Software - CAA

[SPH-4593] Fixed an issue where unit would hang during power-up under certain conditions after recalling a VNA setup from SPA mode.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T

Application Package: V3.30

Release Date : Quarterly Release October 2018

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - TETRA

[SPH-3853] External - Used Training Sequence symbols to determine BER for both allocated and unallocated signal bursts.

*** BUG FIXES ***

-> Software - ISDBT/SFN

[SPH-3731] Fixes an issue where over a 100 ISDBT files were saved into a folder which resulted in the unit slowing down in time. Files are now saved in multiple folders with date and timestamp.

-> Software - VNA

[SPH-4026] Fixes an issue where the application would hang in Transmission Measurement mode when recalling a set up file to put the unit into Cable and Antenna Analyzer Mode, and then attempting to run an OSL calibration.

[SPH-4028] Fixes an issue where the SPA Amplitude Menu would show up in Transmission Measurement Mode.

[SPH-4605] Fixed an issue in VNA mode where glitches would appear at 375MHz and 1500 MHz after a calibration.

-> Software - SPA and Sub-apps

[SPH-3745] Fixed a corner case error with averaging in Interference Analysis Field Strength measurement

[SPH-3951] Disabled the use of Start Freq and Stop Freq in Interference Analysis mode. Center Freq is the proper way to set frequency in this mode.

[SPH-4547] Fixed an issue with field strength limits under V/m units setting

-> Software - TETRA

[SPH-3570] Fixed a bug in TETRA where some units would not recall the correct Tx Output pattern as part of a recalled measurement or setup

[SPH-3943] Fixed an issue in TETRA app where recalling a measurement or setup would not correctly recall the Tx pattern.

-> Software - OBSAI

[SPH-3738] Fixed an issue where the system time would not recall properly under some saved measurement conditions

-> Software - CPRI

[SPH-3738] Fixed an issue where the system time would not recall properly under some saved measurement conditions

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.20

Release Date : Quarterly Release beginning July 2018

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - TETRA

[SPH-4471] Motorola EBTS added to Base Station Selections in Tetra Base Station Sensitivity Tests

-> Software - NB-IoT

[SPH-4569] Fixes an issue where performing a preset does not set the center frequency of the analyzer correctly. Similar behavior can be noticed during setup and measurement

recall.

-> Software - PIM

[SPH-4546] Changed the default F2 frequencies for Option 700 to 764 / 761 MHz for low / high band, respectively.

-> Software - OS/Base

[SPH-4429] Improved battery charge algorithm.

*** BUG FIXES ***

-> Software - DMR2

[SPH-3621] Fixes an issue where the Back soft button is inactivated incorrectly after pressing Max/Min Active Graph soft button

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - NXDN

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - VNA

[SPH-4504] Fixes an issue where in Dual Channel mode, the Smith Chart marker table TR1 and TR2 readout text would overwrite each other.

-> Software - dPMR

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - OS/Base

[SPH-4426] Fixed the issue where saving files to a USB memory via the MMEemory:STORE:JPEG command failed when the usr folder was not present in the USB memory.

-> Software - TETRA

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - NBFM

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - P25/P25p2

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

-> Software - PTC

[SPH-3797] Fixes an issue where ENTER button from keypad to collect new data points from Coverage Mapping doesn't work.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, MS2720T, MT822xB, MT8220T

Application Package: V3.12

Release Date : Quarterly Release beginning April 2018

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - LTE

[SPH-4436] Change MIMO auto detect threshold in LTE and TD-LTE applications, so that the unit is less likely to assume that noise is another active antenna.

-> Software - NB-IoT

[SPH-4545] Initial release of NB-IOT application(option 887)

-> Software - CPRI

[SPH-4551] Initial release for PIM over CPRI functionality(option 754) in MT8220T and MT822xB.

[SPH-4005] Added support in CPRI Base Band Unit Emulation for RRH models RRH2x60-850, RRH2x60-1900A, and RRH2x40-07L-AT

*** BUG FIXES ***

-> Software - LTE

[SPH-3833] Fixed an issue where values for PHICH and PDCCH in LTE application did not export correctly into Master Software Tools.

-> Software - SPA and Sub-apps

[SPH-3940] Fixed an issue in spectrum analyzer mode where adding multiple markers, and/or setting markers beyond the instrument's frequency range, could cause the instrument to lock up.

-> Software - OS/Base

[SPH-4360] Fixed an issue where the GPS information in the title would disappear after recalling a setup file.

-> Software - CPRI

[SPH-3737] Fixes an issue where the waterfall moves in the wrong direction after recalling a measurement file.

[SPH-3537] Fixes an issue where recalled limit lines were drawn at the default values and not at the saved values.

[SPH-4006] Fixed issue where available free space was not displaying during the File Save function.

What will the customer see in this release?

Product : S33xE, S36xE

Application Package: V3.02

Release Date : Special Production Support Release April 2018

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - CAA

[SPH-4491] Resolved issues with new hardware support for production.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V3.00

Release Date : Quarterly Release beginning January 2018

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - CAA

[SPH-3864] Added additional save type Measurement and JPG" to the uWave VNA family."

-> Software - PIM

[SPH-3921] PIM Measurement Tx1 range adjusted to cover 731 MHz to 734.5 MHz

-> Software - VNA

[SPH-3864] Added additional save type Measurement and JPG" to the uWave VNA family."

*** BUG FIXES ***

-> Software - VNA

[SPH-3591] Fixes an issue with Cable Loss mode where limit lines would change after a calibration was completed.

[SPH-3646] Fixes an issue where the touch screen functionality would be disabled due to the Attention" dialog moving behind the main form window."

-> Software - CPRI

[SPH-2932] Fixed an issue in single sweep CPRI Spectrogram where it would not always stop the measurement after one sweep.

[SPH-3536] Fixed an issue - Limits can now only be recalled if the limits were saved in the same mode of operation (SPA, CPRI, OBSAI) as is currently running on the unit.

-> Software - OS/Base

[SPH-3572] Fixed an issue where the GPS tag does not disappear even though GPS is off. This would occur when recalling a trace with GPS data then switching to a live trace and switching modes.

[SPH-3739] Fixed an issue where the unit didn't display an error message when setting the Save Location to USB, then removing the USB, and pressing the camera icon to save a screenshot.

[SPH-3829] Fixed an issue where the option list on the boot up screen was beyond the right edge.

-> Software - OBSAI

[SPH-3536] Fixed an issue - Limits can now only be recalled if the limits were saved in the same mode of operation (SPA, CPRI, OBSAI) as is currently running on the unit.

-> Software - P25/P25p2

[SPH-3321] Fixed an issue with file format. Saving control channel files now places each group of associated data on its own line, when recalled with a text editor.

-> Software - CAA

[SPH-3646] Fixes an issue where the touch screen functionality would be disabled due to the Attention" dialog moving behind the main form window."

[SPH-3837] Fixes an issue where the Dmax value could be manually set to a value that was large then the calculated Dmax value.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T

Application Package: V2.90

Release Date : Quarterly Release beginning October 2017

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - LTE

[SPH-3136] Added Option 886 for 256 QAM extension to FD-LTE and TD-LTE applications

[SPH-3777] Fixed an issue in TD-LTE that would cause constellation to occasionally make bad measurements on valid 256 QAM input signals. (MS2720T Only)

Fixed an issue where changing modes directly to LTE or TD-LTE after a factory default would not correctly display a 256-QAM constellation (MS2720T Only)

[SPH-3188] Added 3GPP Release 13 Spectral Emission Masks for frequencies > 3 GHz in LTE & TD-LTE measurements.

-> Software - PIM

[SPH-3658] SPH-3658 Adds support for the SCPI command MMEMOry:DElete for deleting setup and measurement files.

-> Software - VNA

[SPH-2592] Increases the number of markers from 8 to 12 in VNA mode (mwVNA Instruments, VNA and Field measurement views).

*** IMPROVEMENTS ***

-> Software - DMR2

[SPH-2941] Added remote command to maximize/minimize the active graph type. (See Programming manual for details)

*** BUG FIXES ***

-> Software - VNA

[SPH-2451] Fixes an issue where the Cable List Window was not remaining the top-most form and would move behind the VNA graph.

[SPH-2593] Changes the mwVNA Instruments Limit Line Feature such that each measurement mode can now have independent limit line settings.

-> Software - OS/Base

[SPH-3237] Fixed the issue where using the arrow keys to move around the indoor map was slow in the Spectrum Analyzer mode.

Fixed the issue where moving the cursor around the indoor map failed after recalling a AZM file.

Fixed the issue where pressing the Enter key didn't record data points in indoor map in Spectrum Analyzer mode.

-> Software - NBFM

[SPH-2811] Fixed a bug in NBFM that would cause beep with every sweep when Auto Scan is On.

-> Software - CPRI

[SPH-3029] Fixed a bug that could prevent the second waterfall graph from displaying in a Dual Display recalled spectrogram measurement.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE

Application Package: V2.83

Release Date : Quarterly Release beginning July 2017

Information below may not apply to every model/option in Product list

*** BUG FIXES ***

-> Software - LTE

[SPH-2922] In LTE-EMF mode, when the EMF antenna is disconnected, error messages have been reorganized to have better readability.

[SPH-2924] In WCDMA-EMF mode, when the EMF antenna is disconnected, error messages have been reorganized to have better readability.

-> Software - VNA

[SPH-2594] Fixed an issue with multiple markers and touching the trace, which was causing the nearest marker to become active and move to the touched location. The new behavior is such that touching the trace will result in the marker that is already active to move to the location that was touched.

[SPH-2595] Fixed an issue where when Marker on trace" was set to "All" (in field mode for example) the marker would not update correctly when the start or stop frequency was changed."

-> Software - CPRI

[SPH-2708] Preset now set Spectrogram Record to 'Off' state

[SPH-2898] NOT DONE - Starting with MST V2.36.8 and unit firmware V2.8x, MST will support multiple traces from OBSAI and CPRI applications.

[SPH-2969] Corrected preset values for limit lines in CPRI and OBSAI applications.

[SPH-2970] Fixed a bug where CPRI/OBSAI limit lines would not correctly export to Master Software Tools. Also requires MST v2.36.8

[SPH-2971] Lower Limit line default value corrected in CPRI and OBSAI to match the RF applications

[SPH-3232] Fixed a bug where internal time base would not always lock to external or GPS reference in CPRI mode

-> Software - SPA and Sub-apps

[SPH-2841] Fixes an issue where EMI antenna selection was off by one.

[SPH-3138] Fixes rounding error of BW value in Channel Scanner file after Scriptmaster scan.

-> Software - OS/Base

[SPH-3237] Fixed the issue where using the arrow keys to move around the indoor map was slow in the Spectrum Analyzer mode. Also fixed the issue where moving the cursor around the indoor map failed after recalling a AZM file.

-> Software - OBSAI

[SPH-2975] Fixed a bug where Single Sweep mode would occasionally cause the Layer 2 Alarms display to flicker

-> Software - P25/P25p2

[SPH-3147] Mapping data collection for is now limited to 8 hours or 60,000 points of data collection to avoid memory overrun issues.

-> Software - CAA

[SPH-2424] Fixed an issue where the unit would hang if a SCPI preset was issued and the Cable list table dialog was open.

NOTE: THIS FIX ALSO APPLIES TO THE PIM MASTER.

[SPH-2548] Fixed an issue where the marker would not move when adjusting the twiddle knob to the left.

[SPH-3114] Fixed an issue where Marker-to-Peak and Marker-to-Valley were shifted 1 pixel to the left when recall a measurement file type .dat.

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V2.71

Release Date : Quarterly Release beginning May 2017

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - OBSAI

[SPH-2517] Added OBSAI RF LTE option

-> Software - CPRI

[SPH-2963] Implemented support for Samsung radios which uses IQ mapping method 3

[SPH-3042] Added Samsung Radio Preset to Radio Preset selection

Added ability to select CPRI IQ Mapping method 3

[SPH-3050] Added informational messages that Auto Detect works only with CPRI mapping method 1

[SPH-3052] Added informational messages that Pan and Zoom functions only for Display 1.

[SPH-3053] Fixed a bug to turn off the SFP Tx diode when not in use

*** IMPROVEMENTS ***

-> Software - DMR2

[SPH-2156] Tx Output will now synchronize to Base Station downlink signal

-> Software - VNA

[SPH-2402] The limit line behavior in the Cable and Antenna mode of the BTS Master has been enhanced. With this update, the limit line settings for each measurement type will be unique for that measurement and will persist even if the measurement type is changed.

*** BUG FIXES ***

-> Software - SPA and Sub-apps

[SPH-2337] Fixes an issue where Emission Mask measurements produced erroneous pass/fail results under certain conditions.

[SPH-2504] Fixed an issue where Field Strength measurements in Coverage Mapping did not display the correct results for non-dBm units

-> Software - OS/Base

[SPH-2860] Added support for commands with a block data parameter for the raw socket SCPI interface.

-> Software - TETRA

[SPH-2397] Fixed a bug where saved .mtd files were not correctly storing EVM data.

-> Software - NBFM

[SPH-2891] Fixed a bug in NBFM where changing DCS value could corrupt the Signal Generator pattern outputs for all LMR demod applications

-> Software - CAA

[SPH-2393] Fixed an issue with the Back soft key in the Application Options menu that would not return the user back to the System Menu once they have entered into the Bias Tee menu.

-> Software - PTC

[SPH-2455] SOURce:DM:PATtern and SOURce:DM:PATtern? remote commands are now functional

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V2.60

Release Date : Quarterly Release beginning January 2017

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - DMR2

[SPH-1811] DMR2 Application nomenclature changed to DMR" Remote command remain compatible."

-> Software - CAA

[SPH-2508] Added support for easyTest in the VNA Master (MS20xxB series) and LMR Master (S412E).

[SPH-1506] Added a SCPI command to allow saving of .dat measurement files.

-> Software - LTE

[SPH-2296] Added limited support for TD-LTE 4x4 MIMO

-> Software - VNA

[SPH-2508] Added support for easyTest in the VNA Master (MS20xxB series) and LMR Master (S412E).

[SPH-1506] Added a SCPI command to allow saving of .dat measurement files.

-> Software - CPRI

[SPH-2180] For Option 751 CPRI - Added the ability to show two spectrum or spectrogram graphs which can display up to four separate AxC groups (traces).

[SPH-2448] Added support for CPRI line rate 8 (10.1376 Gbps)

[SPH-2449] Added support for compressed LTE sampling rate on 20 MHz LTE signals

[SPH-2640] Auto Detect improved with Ericsson presets

*** IMPROVEMENTS ***

-> Software - OS/Base

[SPH-2515] Web UI tab removes model information.

*** BUG FIXES ***

-> Software - LTE

[SPH-47] Fixed a bug in LTE EMF recalled measurements where RS values might recall improperly

[SPH-2240] Fixed an issue that prevented 4x4 MIMO time alignment data from recalling properly to unit.

[SPH-2788] Shift-1 Preset is now prevented while a recalled measurement is displayed.

-> Software - SPA and Sub-apps

[SPH-1988] Fixes a bug where the zero span max RBW value was incorrectly limited in the GUI and as a result was out of sync with the actual RBW value.

-> Software - OS/Base

[SPH-1812] Fixed an issue where black on white and color on white schemes were not displaying correctly in some LMR Master modes.

-> Software - HiPM

[SPH-1667] Fixed a bug where the unit would unexpectedly attempt to zero the sensor after recalling a measurement

[SPH-2381] Fixes an issue where the Quick name buttons were not saved with the setup in Hi-PM mode.

-> Software - TETRA

[SPH-2376] Save on Event .csv measurement files are updated to contain results for recently-added RMS Vector Error and Peak Vector Error measurements.

-> Software - VSG

[SPH-1800] BTS Master VSG now allows up to 48 waveforms to be loaded

-> Software - P25/P25p2

[SPH-2373] Fixed an issue that could cause the unit to hang when recalling setups for an application other than the current one.

[SPH-2501] Updated remote DISPlay:TRACe<Tr>:FORMat:SIGAnalyzer command/query parameters to match the Programming Manual.

-> Software - WiMAX

[SPH-2309] Fixed a bug where the unit would intermittently hang when displaying Spectral Emission Mask

What will the customer see in this release?

Product : S33xE, S36xE, MS271xE, MT821xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MT822xB, MT8220T, MW82119B

Application Package: V2.50

Release Date : Quarterly Release beginning October 2016

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - TETRA

[SPH-2147] Added Residual Carrier Magnitude measurement to the Summary display

[SPH-2149] TETRA remote queries :FETCh:SIGAnalyzer? :READ:SIGAnalyzer? :MEASure:SIGAnalyzer? will now contain two additional values in the response for Peak Vector Error and Residual Carrier Magnitude

[SPH-1603] Added Police Digital Trunking Options 563 and 562

-> Software - OS/Base

[SPH-119] Improved error message on LTE trace save failure when trying to save before the end of the first sweep.

-> Software - NBFM

[SPH-1919] Remote command :FETCh:SIGAnalyzer? updated so the second returned value in the string will represent the value indicated by the Summary Freq Disp front panel setting. (Carrier Frequency or Frequency Error)

-> Software - VNA

[SPH-1921] Added select SCPI commands to support VNA Field Mode.

*** BUG FIXES ***

-> Software - VNA

[SPH-2307] Resolved an issue with marker interpolation on Smith Charts or Polar Charts that caused stray lines to be drawn over the entire screen. This issue only affected VNA

mode in the VNA Master products.

-> Software - SPA and Sub-apps

[SPH-282] Fixed an issue where Markers on Result traces do not jump to the right frequency when markers are toggled between traces.

[SPH-2182] In SPA field strength graph, negative antenna factors show correctly over frequency.

-> Software - OS/Base

[SPH-1642] Fixed a typo in the power limit warning message at boot.

[SPH-1653] Clearing old messages when changing modes from a recall state.

[SPH-1681] Fixed a black out of the web interface remote display in Chrome when selecting a different browser tab then selecting the remote display tab.

[SPH-1863] Fixed an issue where SPA application performed a LO Null search on the second application load after a master reset.

[SPH-1889] Fixed a problem where user defined calibration files were getting deleted on entering the PIM application a second time after a master reset.

What will the customer see in this release?

Product : S33xE, S36xE, S412E, MS202xB, MS203xB, MS202xC, MS203xC, MS2720T, MS822xB, MT8220T, MW82119B

Application Package: V2.40

Release Date : Quarterly Release beginning July 2016

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - VNA

[SPH-1744] Added support for interpolated markers in VNA mode. When marker values are set via the numeric keypad or via SCPI, interpolation will be used if the desired marker x-axis value is not an actual measurement point. Markers will continue to snap to the nearest point if the twiddle knob or the arrow keys are used to set their location.

-> Software - dPMR

[SPH-1656] Added remote command support for dPMR.

-> Software - SPA and Sub-apps

[SPH-1914] New trace result types Max Hold and Total Max Hold added to EMF Measurements.

-> Software - OS/Base

[SPH-116] Added Quick Name Matrix support to Transmission Mode.

[SPH-1858] Added EasyTest repeat script capability.

-> Software - TETRA

[SPH-1565] Added remote command support for RMS, Peak Vector Error and Residual Carrier Feed Through.

-> Software - CPRI

[SPH-1804] Added Option 413 Ethernet, which is compatible with all options.

-> Software - P25/P25p2

[SPH-36] P25P2 - Added four new Control Channel summary displays - Active Control Channel Summary, Adjacent Site Summary, Band Plan Summary, Backup Control Channel Summary.

*** IMPROVEMENTS ***

-> Software - OS/Base

[SPH-1510] Fixed an issue where web server popups were showing up off screen on pages that can be scrolled.

*** BUG FIXES ***

-> Software - DMR2

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

-> Software - NXDN

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

-> Software - VNA

[SPH-502] Resolved an issue that prevented the instrument settings from getting preset after a measurement file was recalled.

-> Software - HiPM

[SPH-1606] Fixed a bug in High Accuracy Power Meter mode where max power for the MA24106A sensor could not be set up to +23 dBm.

-> Software - OS/Base

[SPH-104] Fixed an issue where Option 31 (GPS) was listed as an add-on option in MT8220T. It is standard in this model.

[SPH-107] Fixed an issue where instruments would respond to multiple IP addresses.

[SPH-1859] Fixed the issue where the instrument would hang at the last step when executing an easyTest script with the maximum number of steps(500) allowed.

-> Software - SPA and Sub-apps

[SPH-283] VBW set to correct bandwidth in Zero Span after presetting the instrument.

[SPH-284] Enabled ability to turn on Markers after sending Preset command over SCPI.

[SPH-289] Initial attenuation level values are restored after going in and out of Coverage Mapping.

[SPH-298] Fixed an issue where sweep time was not estimated correctly after preset

[SPH-302] Preset SCPI command now resets Auto RBW from Off to On when C/I is turned On.

[SPH-303] RBW/VBW ratio returns to default value after AM/FM/PM mode switching.

[SPH-304] Navigation hard keys when map is not loaded works in Coverage Mapping.

[SPH-305] Fixed an issue where a mode switch, after Esc-On, from SPA into IA and then back into SPA, will cause the Save On Event button to vanish.

[SPH-307] Fixed an issue where IFBW state indicator in the status window displays incorrectly.

[SPH-325] Fixed an issue where recalling a measurement file with field strength units would not recall correctly.

-> Software - TETRA

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

[SPH-1443] Fixed an issue where 'Received Pwr' of the summary display did not show power within acceptable range.

[SPH-1513] TETRA - Fixed a bug where recalled measurements would not correctly populate values in the Summary Table

-> Software - NBFM

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

-> Software - P25/P25p2

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

[SPH-1665] Modified SCPI command to include new Summary display graphs in P25 P2 Analyzer measurement

[SPH-1690] Fixed Motorola Base Station Test in P25 Phase 2 app. Removed additional sampling that was added when when implementing FDMA Control Channel measurement. Additional sampling was causing improper delay estimation for re-sync of signal pattern.

-> Software - PTC

[SPH-660] Fixed an issue with pan and zoom with indoor maps where data points would not zoom in sync with the map.

[SPH-1555] EVM and other summary measurements were adversely affected by PTC burst selection method when frequency offset between transmitter and receiver was more than about 150Hz. The burst selection method was optimized to increase the frequency offset capability to at least +/- 340Hz. This should allow customers to measure the standard of +/- 330Hz Wayside requirement.

Changed 'IQ Imbal' to 'IQ Offset' to better reflect all combined DC offsets (LO leakage, IQ DC Offset, etc...). Measurement now responds to changes in IQ DC Offset injection

What will the customer see in this release?

Product : S33xE/S36xE

Application Package: V2.31

Release Date : June 14, 2016

*** BUG FIXES ***

Cable and Antenna Analyzer [1]

- Corrected the application version number to fix an issue where .vna files from V2.30 would not open in Line Sweep Tools.

What will the customer see in this release?

Product : S33xE/S36xE

Application Package: V2.30

Release Date : May 23, 2016

*** NEW FEATURES ***

General [1]

- Allow WEB server admin login to access all instrument control capabilities. QDF-79

Spectrum Analyzer and Sub-modes [1]

- Added Field Strength measurements to coverage mapping option measurement in SPA mode. #3342

High Accuracy Power Meter [1]

- Added support for MA243xxA USB power sensors.

*** ENHANCEMENTS ***

General [6]

- easyTest will now replace existing measurements with the same name when performing an automatic file save operation associated with Sky Bridge advanced scripts. Refer to Sky Bridge product release notes for individual product/option support.
- Increased the number of easyTest Script steps supported from 100 to 500.
- Substantial updates to Japanese language translation files for SPA and System applications.
- Substantial updates to Chinese language translation files for all applications.
- Updated Signal Standards files to include LTE Bands 29,30,31,32, and 66A to keep up with recent standards releases.
- Added Disclaimer notice on web server login page. QDF-81

*** BUG FIXES ***

General [3]

- Fixed an issue where the instrument would display an incorrect IP address when using a Zyxel mobile router powered by the instrument's USB port. #23728
- Fixed an issue where the status window reported an invalid IP address of 169.254.x.x if the window was opened shortly after the Ethernet cable was plugged in. #23045
- Fixed an issue where the file type warning message was not shown in the Select File Type dialog.

High Accuracy Power Meter [1]

- Fixed an issue with zeroing external USB high accuracy sensors.

What will the customer see in this release?

Product : S33xE/S36xE
Application Package: V2.21
Release Date : March 31, 2016

*** NEW FEATURES ***

General [3]

- Added new administrative features to WEB server: access log and WEB banner settings.
- Added Option 751 for CPRI support in E series products.
- Expanded capabilities to allow easyTest to enable more complex test scripts to be executed. easyTest scripts will also be able to save files to a single directory allowing for a simplified process for retrieving test results. ECAA-9.
Refer to Sky Bridge product release notes for individual product/option support.

*** ENHANCEMENTS ***

General [1]

- Updated the CableList.txt file to add 9 additional cables in response to customer request.

*** BUG FIXES ***

General [1]

- Fixed an issue where the IP address using DHCP was not updating even though there was an Ethernet cable connected in the E series instruments.
This problem was seen only if booting up without the Ethernet cable connected. #23045

Spectrum Analyzer and Sub-modes [3]

- Fixed an issue in coverage mapping where the direction hard keys would not function when a GPS map was not loaded.
- Fixed an issue in SPA mode where 'Save On Event' button was hidden after using IA mapping feature.
- Fixed an issue where recalling a measurement caused the unit to go to the Gated Sweep menu.

What will the customer see in this release?

Product : S33xE/S36xE
Application Package: V1.60
Release Date : November 20, 2015

*** BUG FIXES ***

Spectrum Analyzer and Sub-modes [3]

-

Fixed an issue in SPA mode where 'Save On Event' button was hidden after using IA mapping feature.

- Fixed an issue in coverage mapping where the direction hard keys would not function when a GPS map was not loaded.
- Fixed an issue where a preset was required to re-enable the auto reference level/attenuation coupling after recalling a setup or measurement file where attenuation setting was manual. #21981

What will the customer see in this release?

Product : S33xE/S36xE
Application Package: V1.59
Release Date : September 30, 2015

*** ENHANCEMENTS ***

General [5]

- Added additional monitoring of Battery SMBus to improve the handling of battery charge termination. #23219
- Added the ability to lock an instrument from Telnet and FTP connections.
After setting the remote password and rebooting the unit, the unit will no longer allow Telnet and FTP connections.
To remove the lock, either do a factory reset or remove the remote password by setting it to blank. #22432
- Changed several icons used in Night Vision mode for better visibility. #22831
- The warning that appears when downloading multiple files via the web browser now indicates that the process may make the instrument unresponsive until the download is completed. If there is an error during the process, another message will appear to suggest a smaller download. #22945. #22945
- WEB browser file download attempts are no longer possible with iOS devices. #22499

Spectrum Analyzer and Sub-modes [1]

- Added Pan & Zoom functionality for .azm maps inside Coverage mapping measurements for SPA mode. #3217

Cable and Antenna Analyzer [1]

- The HHST warning message that appears when saving a .dat measurement files with more that 551 points will now only show once on the first save attempt after any reboot. #3424.

*** BUG FIXES ***

General [9]

- Fixed an issue in easyTest execution where a script with auto advance step would run until end when a dialog window was open on the screen. #22554
- Fixed an issue in easyTest menu shortcuts, to test for the existence of the script file, before attempting to execute the script file. #22842
- Fixed an issue in the WEB UI of device where scale on the graph showed incorrect units under certain conditions. #22659
- Fixed an issue in the WEB UI of the device where the 'Menu' button would occasionally not be displayed, when using Internet Explorer version 10/11. #22535
- Fixed an issue in the WEB UI where error messages associated with file save events provide more relevant information as to the cause of the error. #21444
- Fixed an issue in the WEB UI where some elements on the screen were not displayed properly in the browser, in SPA mode. #22659
- Fixed an issue in web server where some of the hardware specifications were wrongly displayed with some device models. #23041
- Fixed an issue that could cause the Quick Name or the Quick Name Matrix button configuration to become undefined after a setup is saved via a remote command or PC tool and recalled at a later time. #22810. #22810
- Fixed an issue where the File type selection in Save dialog was very slow when using the rotary knob. #22559

Spectrum Analyzer and Sub-modes [14]

- Fixed an issue in IA mode where limit settings were not locked when Emissions Mask was turned on. #23092
- Fixed an issue in IA RSSI mode where color of the trace changed erroneously from yellow to red while recalling a measurement. #23007
- Fixed an issue in SPA mode that prevented changing reference level using the rotary knob or arrow keys on the device. #22630
- Fixed an issue in SPA mode where changing the sweep time in Zero Span using the rotary knob or arrow keys would cause the value to fluctuate before settling to the set value. #22803
- Fixed an issue in SPA mode where channel power used to show 0 dBm for smaller span values. #22772
- Fixed an issue in SPA mode where Emission Mask incorrectly reported "Fail" on segments that were actually a "Pass". #21687

- Fixed an issue in SPA mode where enabling Gated Sweep after turning ON channel power measurement would turn off the measurement, when exiting the gated sweep settings menu. #22929
- Fixed an issue in SPA mode where setting detection to Quasi Peak did not allow the correct range of permitted RBW values for this detection standard. #22918
- Fixed an issue in SPA mode where the counter marker showed the marker in the wrong location after changing frequencies. #22400
- Fixed an issue in SPA mode where the marker value shown above the graph area varied from the value shown inside the graph after the marker location was moved with the rotary knob. #22083
- Fixed an issue in SPA mode where the number of points for the limit envelope was not updated properly when the limit envelope shape was changed. #22821
- Fixed an issue in SPA mode where the SCPI command returned values with incorrect number of decimal point precision. #11751
- Fixed an issue in Spectrogram mode where invalid data was shown on screen when the view setting for the trace was set to 'blank'. #22819
- Fixed an issue where Emission Mask would fail at times, even though the measurements were well below the limit lines. #21687

Cable and Antenna Analyzer [4]

- Fixed an issue in Cable and Antenna Analyzer mode during InstaCal download, where a screen touch outside the active message box would close the window and device would go into a frozen state until download completed. #22428
- Fixed an issue in Cable and Antenna Analyzer mode where a screen touch outside any notification window during Calibration would cause the device to go into an unresponsive state. #22428
- Fixed an issue in Cable and Antenna Analyzer mode where presetting the unit after a recall operation could leave the device in an inconsistent state. #22552
- Fixed an issue in Cable and Antenna Analyzer mode where turning the limits ON via SCPI did not work as expected immediately after a factory reset of the instrument. #22461

What will the customer see in this release?

Product : S33xE/S36xE
Application Package: V1.58
Release Date : 6-12-2015

*** NEW FEATURES ***

General [5]

- A small camera icon has been added to the system title bar next to the floppy disk save icon. This touch screen icon can be used to quickly save a screenshot to the last-used save location. #2719
- Added a Web Server function for Ethernet-enabled instruments to allow easy remote control from a HTML 5 WEB browser.
- Added separate message dialog box when deleting folders when file type selection is not set to "All Files" type. #21672
- File sort method and sort order will now be persistent through window closes. #21827
- The configuration of the Quick Name buttons and the Quick Name Matrix is now preserved for future firmware upgrades when selecting the "Save and Restore" option during the firmware upgrade process. Upgrading your firmware to this version will clear the existing configuration, but future firmware upgrades will not. #2715, #2907

Spectrum Analyzer and Sub-modes [5]

- Added commands to check for end of sweep in SPA mode.
 - 1) :[SENSe:]SWEep:STATus? Returns 1 when sweep is complete. Returns 0 when sweep is in progress.
See Programming Manual for details.
- Added warning message when turning on markers 2-6 with marker 1 reference ON.
With Marker 1 reference turned ON, turning on other markers with Delta markers OFF now turns On the Delta Marker with warning message. #21472
- 'Auto Ref Level' button added to Amplitude Menu (in Spectrum Analyzer and Interference Analyzer modes) for quick access. #3045
- Enabled editing center frequency when in RSSI coverage mapping mode. #21664
- Save Measurement and JPG feature added for AM/FM/PM mode. #21670

High Accuracy Power Meter [1]

- Adding support for the MA24208A and MA24218A High Accuracy power sensors.

*** ENHANCEMENTS ***

General [5]

- Changed color for magenta to a darker shade when in "Black on White" Display mode, for better visibility of traces and text. #21738
- Corrected error message displayed to a more meaningful one, when saving files with target memory nearly full. #21966
- Free space on the storage device will be checked before JPGs can be saved. #21369
- Updated the Support File, Antenna.txt in V2.07 to include Anritsu Antenna 2000-1715-R
- Updated the Support File, CableList.txt in V3.06, by adding support for an additional manufacturer of RG58C-U Cable with a propagation velocity of 0.656.

Spectrum Analyzer and Sub-modes [3]

- Display format of amplitude units on graph is now changed. Units are displayed only on top and bottom of the grid. #22145
- GUI updates are now consistent after Spurious Emission segment changes via SCPI. #18981
- When recalling saved setup, invalid channels/frequencies are shown as "--" and readings are masked out corresponding to the invalid channels. #21603

Cable and Antenna Analyzer [1]

- Preset operation from remote is now disallowed when unit is in measurement recall mode. #20961

*** BUG FIXES ***

General [10]

- Changed the Spanish Language translation of ON/OFF to fit within the allowable space of the Marker Table. #22315 #22315
- Fixed an issue in Web interface where the Remote control screen did not show the instrument menu button when accessed through Safari browser. #22158
- Fixed an issue when attempting to set Feb. 29 (a leap year date) before setting the year to a leap year. #21366
- Fixed an issue where a '(null)' was displayed on web server unit buttons. #21038
- Fixed an issue where buttons in web server fast mode showed '0' for their toggle states. #21038
- Fixed an issue where dragging an open dialog box would leave tracers on the screen. #21961
- Fixed an issue where the login button would not work on web UI, when accessing the device remotely with Safari browser. #22155
- Fixed an issue where the web server appeared to lock out when the client PC powered down overnight without logging out of the web server and was assigned a different IP address when powering up the next day. The web server considered it as a different client and it gave the "old" client 2 minutes to keep the connection, so it appeared to lock out. #21740
- Fixed an issue with an overflowing USB SCPI command queue by increasing the buffer size from 50 to 500. #21312
- Fixed an issue with the Support File, Signal Standards in V2.11, Correcting the Starting Channel number for TD_LTE Band 41 (2496-2690 MHz) to 39650. #21874

Spectrum Analyzer and Sub-modes [20]

- Corrected back button behavior in detection menu for SPA mode, to properly return to previous menu.
- Fixed an issue where more than 255 calibration data points were not properly accepted by the device when reading an antenna.txt file. #21854

- Fixed an issue where sweep time was not updated properly when auto sweep time was enabled in SPA mode. #22210
- Fixed an issue where the attenuation level was set incorrectly upon recalling a measurement in IA mode. #21981
- Fixed an issue where the BW could be set to 0 in Channel Scanner Custom Scan list.
This is now limited to 1 Hz. #21960
- Fixed an issue where the Reference Level value returned via SCPI command was erroneous when RL Offset was set to a non zero value. #11751
- Fixed an issue where the Save On Event button would show up in IA Mapping measurement mode. #21471
- Fixed an issue where trace shows erroneous data when sweep mode changes while a sweep is in progress. #21868
- Fixed an issue with selecting a frequency with Mapping mode not locked to GPS, the frequency pop-up obscures part of the GPS warning. GPS message has been moved to prevent the overlap. #22240, #3045
- Fixed an issue with some error messages that erroneously referred to "Time Span" instead of "Recording Time" #21062
- Fixed an issue with Sweep Once when invoked via SCPI command. #18978
- Fixed an issue with the "Distortion/Total Vrms" value returned by the SCPI data query did not match the value displayed in the table. #21597
- Fixed an issue with the header units for Attenuation in Spurious Emission file. #21568
- Fixed an issue with the Input Attenuation setting after loading a saved setup file. #21482
- Fixed an issue with the Limit Envelope Offset when using linear units of measure. #21558
- Fixed issue where RBW could be set to an invalid value in zero span under SPA mode. #21788
- Fixed issue where recalling spectrogram measurement file causes unit reboot. #21952
- Fixed the Auto Save for Spurious Emissions when RBW & VBW are <1 MHz RBW & VBW, showing as 0 Hz. #21208
- Fixed the issue in Channel Scanner mode where power readings and graph were updated in frequency scanner mode, for invalid frequencies. #21603
- Main Channel power no longer shows invalid values when Span is less than Main Channel BW. #20922

Cable and Antenna Analyzer [4]

- Cable list window no longer truncates cable names. #21298
- Fixed an issue preventing the current temperature from updating, while operating outside calibration temperature window. #21076
- Fixed an issue with Signal Standard start/stop frequency calculation.
- When changing start frequency via Left side status touch panel, the other parameters are now properly updated on screen. #21241

What will the customer see in this release?

Product : S33xE/S36xE

Application Package: V1.57

Release Date : Feb. 9, 2015

*** NEW FEATURES ***

General [1]

- Added a Web Server function for Ethernet-enabled instruments to allow easy remote control from any HTML-5 WEB browser.

Spectrum Analyzer and Sub-modes [2]

- Added a new SCPI command, "CALCulate:MARKer#:MAXimum:NEXT" to move the marker to the highest peak anywhere in the trace which is lower than the current marker.
If the given marker is not on, the command turns it on and sets it to the second highest peak in the trace.
The command uses the existing peak threshold values to determine what is and is not a peak.
- User can now select FM scale % values with a minimum of 0.01%.

*** ENHANCEMENTS ***

General [2]

- Files or directories with leading spaces in their names cannot be saved any more.
- The same file type used when SAVING a measurement is initially selected when opening the RECALL measurement dialog.

Spectrum Analyzer and Sub-modes [1]

- Made improvements in Counter Marker accuracy.

*** BUG FIXES ***

General [4]

- Fixed an issue where a Save/Recall message would partially cover the parameter status area.
- Fixed an issue where icons in Save/Recall window were not being updated to match the current color scheme of the device.
- Fixed an issue with changing the instrument device name to close the dialog box cleanly.
- Fixed an issue with the Save/Recall dialog screen size. Enlarged the screen to allow entire warning messages to fit. #20113

Spectrum Analyzer and Sub-modes [5]

- Added a Gate delay maximum value, and set it to 100 ms.
- Fixed an error in the header information generated in Spectral Emissions SPE files.
- Fixed an issue where the average count was not getting reset with the sweep interval in spectrogram. #20609
- Fixed an issue where the spectrogram trace count did not reset with Sweep Interval if the Trace mode was set to average. #20609
- Fixed single sweep not sweeping when manually triggered with auto sweep time turned on.

Cable and Antenna Analyzer [2]

- Fixed an issue where the user could not choose to discard/keep settings from recalled trace, when the recalled trace settings matched the currently running settings.
- Fixed an issue with the "Marker" text when selecting DTF measurement.

High Accuracy Power Meter [1]

- Hi Accuracy Power Meter summary window now correctly clears with preset.

What will the customer see in this release?

Product : S33xE/S36xE

Application Package: V1.56

Release Date : December 5, 2014

*** NEW FEATURES ***

General [2]

- Added an error message pop up during Code Loading to notifying the user in the case the USB stick does not have enough space to store all of the user files from the instrument. #20524
- Added custom Quick Name Matrix information in setup files for PIM, VNA and Cable and Antenna Analyzer applications.

Spectrum Analyzer and Sub-modes [3]

- Added a special key combination (Shft+9+5+3) which loads a frequency calibration button in the System Menus to allow Customer Field Calibration of the 10MHz Reference for SPA only measurements.
See the Maintenance Manual for details on use. #20761

- Added initial support for Isotropic antenna (option 444).
- Added support for easyTest in Spectrum Analyzer application. Requires easyTest V1.05 or greater.

*** ENHANCEMENTS ***

General [12]

- Added a timer that automatically dims the display of the instrument when it is operating under battery power to save power.
"Auto-Dim" feature is enabled in System Options -> Display -> Brightness menu.
Each Model has its own unique default time. Most are approximately 15 minutes. #2521
- Added a warning message to the SAVE FILE dialog to indicate excessive files saved in a single directory, which may slow down file access performance.
- Added ellipses for long names when using quick name matrix buttons. #19341
- Added line-wrapping for option numbers in the System Status dialog. #19979
- Added more improvements to System Level Russian language translations. #19993
- Added more information to an error message that pops up when attempting to run an easyTest script in the wrong application mode. #20775
- Added support for Anritsu antennas 2000-1726-R, 2000-1747-R, and 2000-1748-R
- Displaying >1 hr for sweep time estimates over 1 hour instead of showing ~1.2 hours.
- Improved error handling for WiFi TCP data transfer functions.
- Improved Escape key handling when running easyTest scripts. #19733
- Updated Support files.
Updated the Antenna.txt file to V2.06 by adding 3 antennas.
Updated the CableList.txt file to V3.05 by adding 13 cables.
Updated the Signal Standards File to V2.10 by replacing 43 Standards that had been previously removed. (CDMA, Fixed WiMAX, TD-LTE, and a number of the 700MHz bands)
- Updated System Level Portuguese language support.

Spectrum Analyzer and Sub-modes [12]

- Added a message saying that Spurious Emissions is getting turned off when switching to the unsupported Interference Analyzer mode. #20123
- Added the ability to continue capturing bearings with the MA2700A after switching from Interference Mapping to Interference Analyzer Spectrum measurement. #20585
- Changed minimum value for recalled center frequency to 0 Hz in Spectrum Analyzer application after power cycle. #20021

- Improved counter marker peak search operation. #19891
- Improved Counter Marker Stability. #20559
- Improved reference level offset calculation in Emission Mask. #20204
- Improved zero span narrow VBW performance in Interference Analyzer Spectrum mode. #19248
- Increased maximum value of RSSI time span to 7 days ($60 \times 60 \times 24 \times 7 = 604800$ seconds). #10873
- Limited minimum sweep time entry to 7 us. #20406
- Preset will now default the upper envelope limit number of points to 20. #20182
- Saturation and ADC over-range error messages are cleared more quickly in zero span and IA signal strength modes. #20006
- Selecting "All Measurements Off" now will turn coverage mapping off, so last span will be restored. #19502

Cable and Antenna Analyzer [1]

- Updated Support files.
 - Updated the Antenna.txt file to V2.06 by adding 3 antennas.
 - Updated the CableList.txt file to V3.05 by adding 13 cables.
 - Updated the Signal Standards File to V2.10 by replacing 43 Standards that had been previously removed. (CDMA, Fixed WiMAX, TD-LTE, and a number of the 700MHz bands)

*** BUG FIXES ***

General [14]

- Fixed an issue in Spectrum Analyzer mode that did not show a warning dialog when saving a measurement file with existing filename. #20011
- Fixed an issue in the E series instruments that showed an Ethernet address when not connected. #19768
- Fixed an issue related to defaults on Quick Name features causing unit lockup. #20441
- Fixed an issue where ":MMEMory:DIRectory?" command was returning incorrect filenames and extensions. #19358
- Fixed an issue where "fW" was displayed when "fA" was expected. #20911
- Fixed an issue where a message "Successfully Saved File to USB1" when the save operation actually failed due to the disk being full. #20031
- Fixed an issue where not all files were listed in the Recall dialog. #19989
- Fixed an issue where pressing the back button in the Script Master menu in GSM/EDGE would go to the incorrect menu.
- Fixed an issue where pressing the touchscreen enter key twice when saving a JPEG obscured the graph with the Save dialog. #19775
- Fixed an issue where the instrument would shut down after scrolling to the bottom of the System Status window using the touchscreen. #20675
- Fixed an issue where under unique conditions, the counter marker could show incorrect frequency values. #15953

- Fixed an issue with incorrect values being displayed for marker frequency, for values less than 1 Hz. #15953
- Fixed an issue with limit line value not having enough resolution in Cable and Antenna Analyzer, VSWR, SPA and PIM modes. #10370
- Saving instrument setup on power down has been sped up to prevent loss of setup information.

Spectrum Analyzer and Sub-modes [20]

- Added 0|1 as valid parameters to the SCPI Command ":CALCulate:MARKer:TABLE:STATE" command for consistency with Programming Manual. #20089
- Coverage mapping measurement mode is set properly to default upon performing preset. #20920
- Fixed a problem where manually setting a sweep time with a narrow span on single sweep mode caused a very inaccurate actual sweep time to be reported. #20558
- Fixed a problem with instruments not remembering field strength measurement setup state following power cycle.
- Fixed an intermittent issue with Presetting the instrument in Zero Span Mode. #20439
- Fixed an issue in IA mode where the limit line would not get reset properly following a preset. #19998
- Fixed an issue in Spectrum Analyzer mode that did not show a warning dialog when saving a measurement file with existing filename. #20011
- Fixed an issue involving SCPI command to change Trigger Mode to Free Run. #20257
- Fixed an issue when incrementing or decrementing sweep times with arrow keys or twiddle knob. #19991
- Fixed an issue where ADC Over Range Error message doesn't appear on the screen when a marker was not located within the ADC Over Range area of the trace. #20493
- Fixed an issue where Marker units are sometimes in Hz, in zero span after changing from log amplitude units to linear amplitude units. #20626,
- Fixed an issue where not all files were listed in the Recall dialog. #19989
- Fixed an issue where the Spurious Emission menu could show up in the IA mode. #20123
- Fixed an issue where there were differences between the recalled measurement and JPEG files color and location of vertical reference lines. #20341
- Fixed an issue where under unique conditions, the counter marker could show incorrect frequency values. #15953
- Fixed an issue with "preset" when field strength is enabled. #19595
- Fixed an issue with limit line value not having enough resolution in Cable and Antenna Analyzer, VSWR, SPA and PIM modes. #10370
- Fixed an issue with recalled Spectrogram colors corrected to match the colors during measurement.
- Fixed an issue with Recalling an AM/FM/PM measurement file with a marker on, now retains original marker position rather than snapping to center screen. #20318
- Fixed several issues related to Spurious Emissions not handling Reference Level Offset correctly. #20144

Cable and Antenna Analyzer [11]

- Fixed a problem where after a measurement file recall, GPS status could not be changed
- Fixed a problem where the instrument can start another cal when a cal is already in progress.
- Fixed an issue to restore RF Immunity to its original setting after an RF calibration is aborted. #20584
- Fixed an issue where Cable and Antenna Analyzer no longer produces extra calibration files which could consume all available storage space on the instrument in rare cases. #19627
- Fixed an issue where markers in the 2-port phase measurement didn't report correctly. #20685
- Fixed an issue where the GPS state could not be changed after recalling a Cable and Antenna Analyzer measurement. #20963
- Fixed an issue where the limit line value was reset when the limit on/off is toggled. #20667
- Fixed an issue where the limit value was truncated to the nearest lower integer value. #20667
- Fixed an issue where VSWR limit lines could not be set to certain values. #20545
- Fixed an issue with manual save JPEG step in easyTest scripts which opened the save window with the wrong file type.
- Fixed marker table on/off to allow translation. #19590

High Accuracy Power Meter [1]

- The Save Measurement button in High Accuracy Power Meter now correctly selects a measurement file type instead of a setup file type.

[illegible]

What will the Customer See in this release?

Application Package for SM-E Models (S3xxE): V1.53 SM-E 04-30-2014

General Features

- Fixed an intermittent problem where an EEPROM error message was displayed.
- Fixed a problem where ":SENSe:FREQuency:StARt" SCPI command truncates the last digit when setting frequency beyond 4,294,967,295 Hz.
- Fixed a cosmetic issue with the touchscreen menu display when changing applications.
- Fixed an issue where GPS could not be turned ON or OFF correctly while a recalled Trace was in view, resulting in the On/Off Status being out of sync with button state.
- Fixed an issue where GPS display disappears after preset #17802.
- Corrected a rounding issue from tenths of Hz for frequencies.

- When Remote Access Password is set, it will now display *'s in its entry field
- Remote Access password field touch screen highlight / edit support improved. #18640
- Fixed a possible timing issue when switch mode repeatedly
- Applied Night Vision mode at boot-up. IPL/SPL/ataBoot V3.50 or higher is required, Requires Customer Service Center to update.
- Fixed an issue where sending a mode switch command through SCPI with the mode selector up, would cause the unit to freeze after the mode switch.
- Fixed an issue where multiple IP address fields getting highlighted when scrolling through the fields in the Ethernet Editor. #18622
- Fixed recalling setup file from a different mode #19066
- Changed the color of the power plug prongs icon (when the instrument is plugged in with no battery present) #18597
- Added GPS location in radians to the saved file header.
- Added FW package version to saved file header.
- Updated Russian translation.
- Fixed an issue with negative volts or watts being displayed as huge negative fV/fW values. #14636
- Fix for GUI crash when recalling a different application setup file remotely while an input window is up on the front pannel
: removed any input window before loading a new application. #12975
- Changed behavior of save disk icon to save only measurements to prevent accidental saving of setups instead of measurements.
- Added saving of combined file types for some modes.
- Added support for newer NAND Hardware
- Added support for newer USB Host Hardware
- Improved timing of motherboard self test to prevent false reports of -5.8 Volt Failures
- Added additional error handling for USB incoming communication errors with Windows 7 systems #15322
- Added check for 100% charge, so battery charger won't attempt to restart if the battery is full
- Adjusted the SDRAM clock freq. to eliminate flicker at extreme temperatures.

Spectrum Analyzer Application

-
- Added Out-of-band Spurious emissions measurement.
 - Help images added for certain Generator setups.
 - Fixed a problem when the Reference Level unit is set to Volts or Watts.
 - Fixed a issue with Limit line on a recalled trace.
 - Markers that would exceed the top of the graph area are now flipped below the trace in a downward orientation so they remain visible.

- Fixed an issue where TG Output Power twiddle/arrow key increment amounts were not correct.
- Fixed inconsistency in the precision of the limit value as displayed on the instrument and in LST.
- Updated Chinese translation.
- Updated pre-amp, input attenuation, reference level interactions.
- Adjusted reference level maximum for Field Strength.
- Increased resolution for Sweep Time annotation when in Zero Span
- Fixed a problem with power level displayed when there is a high level power input
- Fixed a problem with recalling a saved working Gated Sweep setup
- Added a safeguard to Prevent a user from starting coverage mapping data collection when GPS is not locked
- Provided RBW delay compensation in zero-span
- Added a minor change for WinLMF operation:
 - improves stability of power measurements in PM mode
 - avoids GUI crash after cable calibration
- Fixed a timing issue causing successive updates to the same parameter to be received out of order in the GUI. #18917
- Fixed an issue where the marker value was not displayed in the upper left corner of the screen When switching from spectrum view in IA mode with a marker displayed to SPA mode, #18394
- Fixed an issue of unit frozen and lost data while doing spectrum monitoring #14811
- Fixed a problem with the Gate-View display when there is no external trigger. #18278
- Disabled Segment Setup in continuous sweep mode. 18898
- Fixed a Zero Span Marker when touch screen interface is used. #11797
- Fixed an issue where the twiddle does not work properly in zero span.
- Removed "Auto Ref Level" button from all SPA submodes except for SPA, PM, and IA.
- Fixed two auto reference level bugs:
 - Wrong RL set when noise marker is turned on #17626
 - Possible hang when units are non-dBm based #17627
- Increase antenna name buffer size so longer names are not truncated. #18714
- Set external trigger line to vertical and interrupted line #18623
- Disabled attempts to load a map in coverage mapping if the map file couldn't be located #18638
- Fixed marker units not getting updated immediately after switching units #18516
- Fixed an issue where auto ref level calculations were incorrect if a delta marker was turned on.
- Fixed an issue where Marker was not being turned on as suggested by the message on the screen when setting the demod frequency to the current marker frequency. #17425
- Fixed recalling of gated sweep setup. #18278

- Added Parameter and SCPI changes for Spurious Emissions measurement.
- Fixed an issue with Spurious Emissions Mask amplitude not set correctly for first segment added to empty table. #18877
- Fixed an issue properly scaling the volume level parameter when setting the sound device. #18239
- Fixed an issue preventing triggering from working while in IA spectrum zero span mode. #12671
- Fixed a defect where Video trigger level with RL Offset was not displayed properly. #198098 & #11523

Interference Analyzer Application

- Added MA2700A support.
- Adding MA2700A Calibration images.
- Fixed a problem with Signal ID when the span is much wider than the bandwidth of the generated signal.
- Fixed a problem with Reset/Restart Measurement soft key in spectrogram not resetting the max hold accumulation.
- The messaging when in Single Sweep was not consistent with the functionality of the instrument, this has been fixed.
- Fixed a problem with adjusting Recording Time with the knob in Spectrogram mode
- Increased tone rate for Signal Strength. Requires CPU FPGA V1.02 or 1.25. Requires Customer Service Center to update.
- Fixed an issue with Burst Detection where it stopped functioning with certain key sequence
- Sweep Interval will have effect only if selected trace is in Max or Min Hold.
- Spectrogram display is now for the selected trace.
- Spectrogram Status window changed.
- Added Spectrogram stitch feature for Master Software Tools.
- Added maximum and minimum values for the Reference Level.
- Fixed a problem with recalling a spectrogram file from Spectrum does not restore all the parameters correctly and the graph inaccurate. #17962
- Fixed auto ref level not working in IA mode.
- Fixed recalling setups from the shortcut menu stops all measurements. #18880
- Fixed an issue where mapping was not allowed with the default map.
- Added a deleting all points confirm window when the button Delete All Points in Coverage Mapping menu is selected. #18221
- Improved IA AutoScale in RSSI so trace stays on screen. #17657
- Fixed issue where coverage mapping points did not map correctly on touch screens if base jpg was smaller than the map region on the screen. #17810
- Fixed colors for coverage mapping plotted points and RSSI value. #14673

Channel Scanner Application

- Fixed an issue where the instrument could hang if different rows were selected in the Channel Scanner Custom List Edit dialog.

AM-FM-PM Analyzer

- Fixed squelch amplitude bug in AM demod below 8 MHz #18621
- Fixed a problem with displaying large marker table

Vector Network Analyzer Application

- Addressed an issue which was causing the Memory trace frequency axis to be incorrect if the number of points were changed after the display was set to Trace and Memory. #19224
- Addressed an issue where the limit line showed up as a single point when the limit was turned on with the sweep in hold.
- Addressed an issue where the Marker step size was not getting correctly reduced after reducing the number of points in a sweep, causing the twiddle knob to appear less responsive.
- Updated Cable List to V3.04
- Added a check the available disk space before starting the calibration to prevent Calibration off error messages. #17659, 17660.
- Fixed an issue where the Marker Menu appears unexpectedly when choosing a Measurement mode. #18711
- Fixed issue where the Cal will hang during an OPEN step when in single sweep and RF ON OFF is set to OFF. #18625 & 19092
- Changed the label from "Window" to "Windowing". #18289
- Fixed an issue with SetMarker not snapping to the closest data point.
- Fixed an issue where Autoscale was adjusting bottom beyond minimum value. #12362
- Fixed an issue limiting resolution of limit line adjustment in VSWR measurement modes #18875
- Modified SCPI command "trace:data?" to bottom out at -120 dB to match what is seen on the screen on the instrument.

Transmission Mode

- No changes

[illegible]

Application Package for SM-E Models (S3xxE): V1.51 SM-E 08-26-2013

- Copyright© ANRITSU. All rights reserved.

- Fixed an issue where GPS status could become out of sync with GPS coordinates displayed when GPS is OFF.
- Fixed an issue with setting the date to Feb 29 on a leap year.
- Corrected a rounding issue for CENTI_HZ parameter types.
- Button text changes in System Display Settings menu.
- Added an EEPROM snapshot feature for troubleshooting. A folder named "Anritsu_Snapshot" in the internal memory can be deleted for security purposes. This feature does not apply to units with option 7.

Spectrum Analyzer

- Tracking Generator normalization no longer uses Trace Math. Trace A contains the normalized trace and the scale on the left is updated appropriately. Traces B & C now available for Trace Math.
- Transmission Menu updated (New Scale adjustment buttons). SCPI also updated (pl see Garnet PM).
- Added the text "Trans" when Normalization is turned On.
- Help images added for certain Generator setups.
- Added MA2700A support.
- Added .azm support for IA Mapping.
 - .azm maps are zoomable and panable.
 - .azm maps are created via easyMap.
- Fixed an issue with Max Hold in Field Strength.
- Fixed a problem with Set Marker to Channel.
- Fixed a problem with turning on QP detection when VBW type is as Log.
- Fixed a problem when the Reference Level unit is set to Volts or Watts.
- Fixed a problem with the Counter Marker units in Field Strength.
- Fixed a Sweep Time problem when RBW is narrow.
- Fixed firmware crashing when touching the button on the upper right corner of display all traces window.
- Fixed an issue where the GPS reference frequency does not always lock.
- Changed the Preamp warning message to reflect the Reference Level Offset.
- Fixed an issue where the wrong units were displayed while measuring channel power in units other than dBm.
- Disabled the Units menu while in Spectrogram mode.
- Fixed an issue with Limit Envelope not working correctly if the units were Volts or Watts.
- Fixed shape cal instruction available in service mode.
- Fixed an issue where KML(2D,3D) and Mapping Tab Delimited file types could not be selected or saved from File Save menu.

- Fixed an issue where certain parameters were converted to selected units during an increment/decrement operation resulting in a wrong display.
- The limit line will now stay visible regardless of which traces are visible or blanked.
- Fixed an issue where file recall during Save On Event crashes the unit. The operation is not permitted and a warning message has been added.
- Fixed an issue where Trace B was not visible by default after recalling a C/I measurement.
- C/I measurement "Min Sweep Time" button is now correctly labeled "Sweep Time".
- Fixed an issue where Bias-T is not turned Off during a sub-mode switch or when Power & BW measurements or Coverage Mapping is turned On.
- Fixed an issue where the instrument could hang if different rows were selected in the Channel Scanner Custom List Edit dialog.
- Fixed coupling of RBW and VBW in signal strength or RSSI with RBW and VBW in non-zero-span spectrum analyzer.
- Markers that would exceed the top of the graph area are now flipped below the trace in a downward orientation so they remain visible.
- Fixed an issue where TG Output Power twiddle/arrow key increment amounts were not correct.
- Fixed inconsistency in the precision of the limit value as displayed on the instrument and in LST.
- Updated Russian translation.

Interference Analyzer

- Trace Math is now available in Spectrogram.
- GPS data is now recorded with each Spectrogram trace.
- Updated Spectrogram menu.
- Sweep Interval will have effect only if selected trace is in Max or Min Hold.
- Recording Time button is only visible when Record is On.
- Spectrogram display is now for the selected trace.
- Spectrogram Status window changed.
- Added Spectrogram stitch feature for Master Software Tools.
- Fixed a problem with Signal ID when the span is much wider than the bandwidth of the generated signal.
- Fixed a problem with Reset/Restart Measurement soft key in spectrogram not resetting the max hold accumulation.
- The messaging when in Single Sweep was not consistent with the functionality of the instrument, this has been fixed.

Channel Scanner

- Added boundaries for the Reference Level.
- Adjusted the frequency range for some models.
- Fixed ddc failure and error when choosing certain signal standard in channel scanner.

- Fixed an issue with Frequency Scanner allowing set channels to exceed the instrument's sweep range.

AM-FM-PM Analyzer

- Fixed a problem with the sound output in Audio Demod.

CWSG

- Fixed an issue where CWSG setup files could not be recalled from other modes.
- Fixed a problem where "Center Freq" text covered the meter numbers.
- Fixed an issue where Sig Gen app allowed user to adjust in 0.1 dB steps on Rev 1 hardware.

PIM Analyzer

- Mode switching into PIM would sometimes result in an artifact on the screen, this has been fixed.

Power Meter

- Fixed a problem with the Last Span button.

Cable and Antenna Analyzer

- Improved user feedback after a calibration by providing the valid temperature range for the cal that was just completed.
Also, added information to the display of the cal temp range when the calibration becomes invalid.
- Resolved an issue with unit locking up when attempting to recall a DTF measurement from a .dat file.
- Resolved an issue with Peak/Valley markers not working consistently in Transmission Mode while calibration is applied.
- Resolved an issue which was causing confusion when the filetype was chosen using the Filetype drop down box, resulting in measurement files being saved as setup files.
- Resolved an issue with the unit hanging up when dialog windows were allowed to be moved using the touch screen.
- Resolved an issue with SWR autoscale maximum amplitude being set to 260.
- Resolved an issue with a calibrated Return Loss measurement displaying incorrectly after the instrument is re-booted multiple times.

High Accuracy Power Meter

- ### Transmission Mode

- [illegible]

Application Package for SM-E Models (S3xxE): V1.48 SM-E 03-8-2013

Internal Release: support for change in anti-backlash setting in LO2.

[illegible]

Application Package for SM-E Models (S3xxE): V1.46 SM-E 09-27-2012

General Features

- ## Spectrum Analyzer

- Fixed a problem where the trace resembles shark fins/saw tooth waveforms in Tracking Generator when RBW was set to 1 Hz
- Fixed a transient spike issue in Tracking Generator when the Generator Output is connected to an external/different SPA
- Fixed a problem when moving markers using touch screen in zero span

Interference Analyzer

- No changes

Channel Scanner

- Fixed a DDC error when selected signal standards have span less than ~40 MHz.

PIM Analyzer

- fixed a calculation bug in max distance and DTP for 850 models

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Fixed a problem of unit hanging after a self test was triggered while sweep was on hold and 'RFPWR WHEN IN HOLD' is set to OFF.
- Fixed a problem with Flex Cal when it is triggered in Single Sweep mode.

Transmission Mode

- No changes

[illegible]

[illegible]

What will the Customer See in this release?

Application Package for SM-E Models (S3xxE): V1.45 SM-E 07-13-2012

General Features

- Fixed a Menu Shortcut issue when it's used to recall files.
- Japanese language translation updated

Spectrum Analyzer

- No changes

AM-FM-PM Analyzer

- No changes

Interference Analyzer

- No changes

Channel Scanner

- No changes

PIM Analyzer

- No changes

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Fixed save/recall issues with Menu Shortcut and remote commands
- Leaving the unit's pre-existing cal in place when recalling a setup not containing a cal, when the setup is compatible with the unit's cal setup.
- Japanese language translation updated

Transmission Mode

- No changes

[illegible][illegible]

What will the Customer See in this release?

Application Package for SM-E Models (S3xxE): V1.43 SM-E 06-14-2012

General Features

- Added PIM application to MS2711E
- Updated Japanese translation

Spectrum Analyzer

- No changes

AM-FM-PM Analyzer

- No changes

Interference Analyzer

- No changes

Channel Scanner

- No changes

PIM Analyzer

- No changes

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Enabled Easy Test
- Fixed some save/recall issues
- Updated Japanese translation
- Known defect: Please be advised that recalling a VNA setup file with cal via Menu Shortcut will cause the unit to crash. A power recycle is required for the unit to recover. Please recall via the file menu (Shift-7).

Transmission Mode

- [illegible]

Application Package for SM-E Models (S3xxE): V1.42 SM-E 04-18-2012

- ## Spectrum Analyzer

- ## AM-FM-PM Analyzer

- ## Interference Analyzer

- Copyright© ANRITSU. All rights reserved.

Channel Scanner

- Fixed a bug that would cause Bias Tee output voltage to increase after performing a preset. Bias Tee will now be turned off after performing a Preset

PIM Analyzer

- Reset MW8209A 900MHz upper frequency limit from 970MHz to 960MHz.
- Added additional Cal/Measure capability for MW8208A DTP measurement
- Implemented PIM SCPI command for changing between DTP and PIM.
- Bug fix to keep display from updating PIM measurement during DTP Cal.

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Added 75ohms for Smith Chart
- Added popup message after calibration
- Recalling cals only when serial numbers match
- Added functionality to have limits work with bounded markers
- Cable Loss Average is now saved in the setup file
- Fixed a boot up problem when power is set to LOW
- Fixed problems related to Quick Name Matrix
- Fixed a problem related to DAT file creation

Transmission Mode

- [illegible]

General Features

Spectrum Analyzer

- ## AM-FM-PM Analyzer

- ## Interference Analyzer

- ## Channel Scanner

- ## PIM Analyzer

- Copyright© ANRITSU. All rights reserved.

Power Meter

- No changes

High Accuracy Power Meter

.....

- No changes

Cable and Antenna Analyzer

- No changes

Transmission Measurement Mode

- No changes

[illegible]

Application Package for SM-E Models (S3xxE): V1.36 SM-E 11-8-2011

General Features

- Added a new feature which automatically pops up a firmware update window when a USB stick containing the firmware is attached to the instrument.

Spectrum Analyzer

- Fixed the problem of which marker jumps onto trace A when user presses button to search next peak to the left/right.
- Stopped displaying antenna factor in field strength measurement if the spectrum measurement is outside of the valid antenna's frequencies.
- Disallow recalling of a setup if the instrument is in measurement recall mode.

AM-FM-PM Analyzer

- No changes

Interference Analyzer

- Fixed the problem of which the spectrum sweep doesn't reset after it has been recorded into the spectrogram trace under some circumstances.

Channel Scanner

- Fixed the problem of which the signal standard list window was dismissed prematurely when user has selected an invalid signal standard such as "NONE."

PIM Analyzer

- Added support the new PIM Master model MW8209A
- Cable list is now shared with the cable and antenna analyzer measurement mode.
- Changed the way calibration is performed in distance-to-PIM mode.

Power Meter

- No changes

High Accuracy Power Meter

- Added support for the new power sensor model MA24240A, and MA24105A.

Cable and Antenna Analyzer

- No changes

Transmission Measurement Mode

- No changes

[illegible]

Application Package for SM-E Models (S3xxE): V1.30_SM-E 8-25-2011

General Features

- Fixed a problem where a saved JPEG file could be empty.

Spectrum Analyzer

- No changes

AM-FM-PM Analyzer

- No changes

Interference Analyzer

- No changes

Channel Scanner

- No changes

PIM Analyzer

- No changes

- Added squelch function
- Limited center freq to above 5KHz
- Made audio demod mode and AMFMPM coverage mode mutually exclusive

Interference Analyzer

- No changes

Channel Scanner

- No changes

PIM Analyzer

- No changes

Power Meter

- Fix adjusted the color in black & White color scheme so that the readout is more visible

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Improved RF immunity
- Added support for the new .dat format, version UDF 1.00, which is supported by Line Sweep Tools V1.20.
- New Limit 'Warning' message. Made limit message bolder and bigger when the limit message change state
- Modified the Status window made to appear similar to SPA.
- Fixed a problem with recalling setups with cal.

- Fixed a recall problem with markers.
- Fixed a recall problem with start/stop frequency when a signal standard is used.
- Fixed a recall problem when distance values exceed 1500 in feet.
- Fixed a problem with the favorite cable list.

Transmission Measurement Mode

- No changes

[illegible]

Application Package for SM-E Models (S3xxE): V1.27 SM-E 5-09-2011

General Features

- Temperature reading in status window now displays both in Celsius and Fahrenheit
- Fixed a bug that would sometimes include the save dialog when saving as a jpeg
- Touching parameters on the left annotation area will now activate the parameter for editing (with some exceptions)

Spectrum Analyzer

- Fixed a bug where Save-on-event would continue to save after switching to other modes
- Fixed a bug in the saved measurement file that caused Reference Level Offset to be incorrectly read and applied in Master Software Tools
- Fixed a bug where Quasi-peak detection wouldn't use the correct CISPR RBW filters

AM-FM-PM Analyzer

- Added Coverage Mapping feature

Interference Analyzer

- Improved timing accuracy of sweep interval in RSSI

Channel Scanner

- No changes

PIM Analyzer

.....

- PIM Analyzer mode is now standard on all models that include Spectrum Analyzer (no longer tied to the option 419)
- Added support for Distance-to-PIM measurement for PIM Master with option 420.

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- No changes

Transmission Mode

- No changes

[illegible]

General Caution

What will the Customer See in this release?

Application Package for SM-E Models (S3xxE): V1.25 SM-E 3-23-2011

- Fixed a mode switch hang-up in units with option 411 installed
- Fixed a false EEPROM Failure in units with Option 411 installed

- No changes

- No changes

- No changes

- No changes

PIM Analyzer

.....

- No changes

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Transmission Mode

- No changes

Cable and Antenna Analyzer

- No changes

[illegible][illegible]

General Caution

If an unintentional failure occurs during the firmware update process, recovery is possible using the Emergency Repair feature through a USB Host connection (i.e., a USB stick).

What will the Customer See in this release?

[illegible]

Application Package for SM-E Models (S3xxE): V1.23_SM-E 2-23-2011

General Features

-
- Fixed option 411 problem with mode switch
 - Fixed a lockup problem with multiple saves
 - Added the display of Fahrenheit for temperature in the System Status window

Spectrum Analyzer

- In Coverage Mapping, user can now retrieve GPS altitude information via SCPI commands, and saved tab delimited and/or KML files
- Added quick key access, and screen touch access to SPA measurement settings in Coverage Mapping
- Added color legends for setting threshold levels in Coverage Mapping
- Fixed units in RSSI Coverage Mapping
- Added the display of frequency range in the antenna table
- Added the display of a frequency offset
- Added the display of Fahrenheit for temperature in the SelfTest window
- Fixed display issues when switching from SPA to AM/FM/PM
- Fixed problems in zero span where IF bandwidth appears different than what is set to

AM-FM-PM Analyzer

- Fixed an issue with power offset
- Added SCPI commands

Interference Analyzer

- Fixed a bug where the 'Save' window would also be saved when saving to jpeg from Spectrogram measurements.
- In Interference Mapping, user can now retrieve GPS altitude information via SCPI commands, and saved tab delimited and KML files

Channel Scanner

- Fixed several bugs related to Script Master
- Fixed a frequency range discrepancy to the model frequency range.

PIM Analyzer

- No changes

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Transmission Mode

- Fixed a problem with displaying Power Levels after a recall

Cable and Antenna Analyzer

- Addressed some issues with recalling setups with calibration. Combined cal file with the setup file
- Turns off cal and displays an error msg when temperature is out of the cal valid range
- Linked the limit Pass/Fail to the bounded Markers (M5 and M6)
- Added the display of Fahrenheit for temperature in the SelfTest window
- Fixed various issues related to limits
- Fixed a problem with DTF Aid screen
- Fixed the Distance display when changing units in Dual Display
- Fixed a Marker table display issue after a recall
- Fixed a Marker frequency display error
- Fixed some marker issues with Save and Recall
- Added the display of the temperature range where the calibration is valid
- Fixed defects related to Marker SCPI commands
- Fixed a improperly formatted block header returned from the :trace:data?
- Added favorites for Cable list

- Fixed an issue with Ethernet (option 411) when recalling a SPA setup file

[illegible]

Application Package for SM-E Models (S3xxE): V1.21 SM-E 11-11-2010

General Features

- The parameter being edited is now displayed in a larger white color font for better readability in poor lighting
- Some improvements to the speed of switching modes (varies with modes).
- Power Offset is now a shared parameter across modes.

Spectrum Analyzer

- Overhaul of the User Interface (see New Measurement Guide 10580-00244 for more details)
 - More setup information is now displayed on the left edge of the screen.
 - Amplitude menu
 - Reference Level Offset is now more consistent with 'Power Offset' used in other modes.
It now accepts 'Gain' or 'Loss' as terminators and the value is shared with other modes by default.
 - BW menu
 - RBW and VBW values are now maintained separately for zero-span measurements.
 - The default value of Span/RBW is now 100.
 - A new button to change VBW average type to Log.
 - Marker menu
 - A 'Large' setting is now available for the Marker table to view marker readout in a large font.
 - Trace menu
 - A new Trace Info button is now available in the Trace menu to show a concise listing of all parameters for the selected trace.
 - 'Reset Sweep' button has been renamed to 'Reset Trace' and moved to the Trace menu.
 - Sweep menu
 - 'Manual Trigger' is now called 'Sweep Once'.
 - A new 'Sweep n Averages' button has been added to allow a full set of averages to sweep when the sweep

is set to Single.

- A new Sweep Mode button (only certain models) allows users to control the sweep algorithm.
- A new 'Auto Sweep Time' button has been added.
- Trigger sub-menu has been revamped with the ability to add hysteresis to the video trigger level.
- Gated Sweep Setup (Option 90) is now more responsive and has separate controls for the gate view (zero span).

- Improvements and bug fixes to the Field Strength measurement.

Coverage Mapping

- Changed the VBW default value for Coverage Mapping to 10 Hz.
- RSSI for Coverage Mapping is calculated using more averaging.
- Changed the minimum sweep time to 250ms.

Interference Analyzer

- Fixed a bug where the 'Save' window would also be saved when saving to jpeg from Spectrogram measurements.

Channel Scanner

- Fixed several bugs related to Script Master.

PIM Analyzer

- Initial Release

Power Meter

- No changes

High Accuracy Power Meter

- No changes

Cable and Antenna Analyzer

- Fixed a bug in DTF Aid.
- Fixed an error in how frequencies are saved in .VNA files.
- Fixed a bug that would cause garbage values in the delta marker if the ref. marker is out of scope.

[illegible]

Application Package for SM-E Models (S3xxE): V1.11 SM-E 7-23-2010

General Features

- Added the "none" selection in signal standard.
- Improvements in save/recall functions.
- Added new translations for Chinese, Japanese, German, Korean and French.
- Fixed an issue with ?save as JPEG? in several modes where an additional measurement was performed before performing the save operation.

Spectrum Analyzer:

- Added support for Option 431 - Coverage Mapping
- Added a "Sweep Mode" button in the Sweep Menu that allows a new "Fast" sweep mode which can be up to 10 times faster. This new feature requires a new Shape Cal.
- Fixed a problem with limits when units are changed.
- Save on Event now saves to the location specified in the save menu
- Fixed problem with recalling setups from a different application.
- Fixed Emission mask lockup if more than 21 mask segments.

- Restrict Zero Span RBW to 1 MHz when entering using numeric keypad

Cable & Antenna Analyzer:

- Added quick name matrix in the Save menu.
- Added user selectable choice to turn off RF power when it is in Hold
- Added limit Pass/Fail message
- Modified cable loss computation for DTF below 1 GHz so that cable loss values below 500 MHz are better approximated
- Cable list updated to 3.03.
- Increased FlexCal resolution. When an old FlexCal is recalled, a message will be displayed to recommend re-calibration.
- Fixed limit display/recall problems.
- Fixed a marker table on/off status problem.
- Fixed a problem with Clear Limit.
- Clear the limit in DTF and Cable Loss when Preset.
- Fixed some minor issues associated with mode change to VVM mode
- Added warning messages for improper settings in DTF.
- Added code to show the file name when it is recalled.
- Fixed some issues with dual display.
- check for dist domain to return proper 'X' values for mkr and limit in remote cmd.
- Fixed the REAL format for the Trace? SCPI command

Transmission Measurement:

- Fixed a limit scaling issue

Channel Scanner:

- Fixed issue where unit would crash if the user pressed enter on an open and empty ScriptMaster setup file selector list.

Power Meter

- Fixed a minor auto scale problem.

Interference Analyzer:

- Added mapping feature.
- Added a ?Sweep Mode? button in the Sweep Menu that allows a new ?Fast? sweep mode which can be up to 10 times faster. This new feature requires a new Shape Cal.

[illegible]

Application Package for SM-E Models (S3xxE): V1.06 SM-E 2-26-2010

General Features

- Added code to check model numbers before code loading with a USB stick

[illegible]

Application Package for SM-E Models (S3xxE): V1.05 SM-E 12-12-2009

General Features

Added new color schemes, accessible in the system options menu.

Fixed a missing '9' key case in the touch screen keyboard.

Added error message when copying file was not successful.

Spectrum Analyzer:

- Fixed a problem with average count display with recalled traces.
- Fixed a problem with switching to Quasi-peak with Auto-RBW.
- Fixed an issue with opening Antenna list in Field Strength measurement.
- Fixed a problem with recalling gated sweep parameters during recall setup.
- Fixed a problem of Trace count not resetting when changing Reference Level.
- Fix for Delta marker unit in zero span.
- Fix for displaying proper Amplitude menu in Field Strength measurement.

Cable & Antenna Analyzer:

- Improved the sweep speed reading.
- Stabilized the cable loss average number when changing the number of points.
- Allowing Markers to be associated to the current trace after a recall.
- Added Marker resolution for data points more than 551.
- Fixed a problem with the display in the Amplitude key when going from top to bottom in the dual display mode.
- Fixed a problem with limits in different measurements.
- Fixed a problem with markers in different measurements.
- Allowing files to be saved in .DAT format that is viewable with HHST V6.61.
- Added VVM option, for specials only at this time.

Interference Analyzer:

- Fix for the IA mode Signal ID measurement relics.
- Fix for IA Recall spectrogram being recalled inverted.

Channel Scanner:

- Update the channel numbers in the graph area when one changes the channel step size or the channel number.
- In channel scanner mode, fix for span and freq step value display on the left side of the screen to be correlated to the values edited by the users.
- Improved power reading accuracy.

High Accuracy Power Meter:

- No Change.

AM/FM/PM mode:

- Initial release.

[illegible]

Application Package for SM-E Models (S3xxE): V1.00 SM-E 08-10-2009

General Features

V1.00 is the initial release for Customers