

MU909814B/15B

μOTDR Module (Chinese)

Release Note

Version 4.04

Thank you for choosing the Anritsu MU909814B/15B μOTDR Module.

This release note explains the functions updated by firmware version 4.04 for the μOTDR Module.

It also provides notes on known software issues and usage precautions.

This release note deals with the firmware whose model name is described in the following:

MU909814B, MU909815B

NOTE: Your μOTDR Module has unique firmware version depending on the model type you purchased. If your model name is found in the following, please download the relevant firmware. This document does not cover the firmware for the following models.

MU909814C, MU909815C

Contents

Item	Description
1. Release Software and Manuals ...P3	Lists software and manuals included in this upgrade
2. Upgrade Target Models ...P3	Lists models supporting this firmware upgrade
3. Version Information ...P3	Lists software versions
4. New Features ...P4	List new functions
5. Resolved Software Issues ...P12	Lists improvements provided by version 4.04 upgrade
6. Known Problems ...P16	Lists known problems
7. Cautions ...P16	Lists cautions for use of MU909814B/15B
8. Upgrade Precautions ...P17	Provides important information about upgrading to version 4.04

1. Release Software and Manuals

This upgrade contains the following MU909814B/15B Series software and manuals.

Download File Name	Version
MU909814B/15B Firmware Version	4.04
Operation Manual	Edition
MU909014A/A1/B/B1/C/C6 MU909015A6/B/B1/C/C6 Operation Manual	28.0

2. Target Models

This firmware supports the following models in the MU909814B/15B.

MU909814B and MU909815B

3. Version Information

This table shows the firmware version. Confirm the firmware version of your MU909814B/15B at the Self Test screen.

Product Name	Version
MU909814B/15B Firmware Update File	4.04

4. New Features

Function added and changed by upgrading the firmware version from 4.02 to 4.04.

- None.

It is not possible to downgrade to firmware prior to 4.02 when V4.04 was installed.

Function added and changed by upgrading the firmware version from 4.01 to 4.02.

- None.

Function added and changed by upgrading the firmware version from 4.00 to 4.01.

- Supported the G0306C video inspection probe.

Function added and changed by upgrading the firmware version from 3.05 to 4.00.

- None.

Function added and changed by upgrading the firmware version from 3.04 to 3.05.

- None.

Function added and changed by upgrading the firmware version from 3.03 to 3.04.

- Changed the Remote GUI function not to use Adobe Flash.
There is no change in the remote GUI function itself.

Function added and changed by upgrading the firmware version from 3.00 to 3.03.

- None.

Function added and changed by upgrading the firmware version from 2.35 to 3.00.

- Supported the MT9090A-001 option for μOTDR Module.

Function added and changed by upgrading the firmware version from 2.34 to 2.35.

- None.

Function added and changed by upgrading the firmware version from 2.33 to 2.34.

- In PON setting, 2 × 8 splitter can be selected.

Function added and changed by upgrading the firmware version from 2.32 to 2.33.

- None

Function added and changed by upgrading the firmware version from 2.31 to 2.32.

- None

Function added and changed by upgrading the firmware version from 2.30 to 2.31.

- None

Function added and changed by upgrading the firmware version from 2.29 to 2.30.

- Added selectable pulse width in distance range of 1 to 50 km.
Please refer to the operation manual for combination.
- Added 1579nm in Power Meter.

Function added and changed by upgrading the firmware version from 2.28 to 2.29.

- None

Function added and changed by upgrading the firmware version from 2.27 to 2.28.

- None

Function added and changed by upgrading the firmware version from 2.26 to 2.27.

- Supported the G0306B video inspection probe. G0306B can be used 60 degrees tip.
- Fiber Visualizer can output multiple VIP images (up to six) in PDF report.

Function added and changed by upgrading the firmware version from 2.25 to 2.26.

- None

Function added and changed by upgrading the firmware version from 2.24 to 2.25.

- None

Function added and changed by upgrading the firmware version from 2.23 to 2.24.

- The starting point (zero-point) of the measured fiber can be set.
The starting point can be set by event number or distance. To edit the setting, select [3] tab on the Setup screen. (Offset the relative measurement for setting by distance.)
- A non-reflective event value with the largest loss can be output as Max Splice for summary. “—” is output when no non-reflective event exists.

Function added and changed by upgrading the firmware version from 2.22 to 2.23.

- The summary of the measurement results can be output in text format from the selected SOR file(s).
The summary includes below.
 - The header information such as measuring instrument name, time and date, etc.
 - Wavelength and total fiber loss, event number, etc.To create a summary, press the Menu key on the Top menu to select Create Summary.
- The header information can be saved in SOR or XML files.
Cable ID, Location, Direction, etc. can be input as the header information.
The Header Input screen is displayed when Header (F2 key) is pressed on the Save screen.
- When turn Off the power, POWERING DOWN is displayed on the screen.
- The Event Edit function of Fiber Visualizer allows editing event type(s) regardless of the thresholds on the Analysis Setup screen.
The reflective, non-reflective, grouped, splitter, and macro bend events can be always changed to any type of splitter event and far-end event.

Function added and changed by upgrading the firmware version from 2.21 to 2.22.

- The following have been made possible by adding the PON configuration settings to the Test Setup screen:
 - Pass/Fail evaluation, by the number of branches in splitter
 - Collective setting of the splitter detection threshold values, by the number of branches, in the Analysis Setup screen.
 - Viewing the number of branches in splitter in the event table
 - Adding the Splitter information to XML file, by the number of branches
- Pulse width can be changed automatically when measuring by Full Auto with Fiber Visualizer. Events can be detected more accurately by composing the events detected by each pulse.
- Added “ZIP” to Saving Format. SOR files of 2 wavelength measurement can be saved and loaded in a single ZIP file.
- Editing Event Type is available while Mode (F2 key): Event Edit is selected on the Events screen of Fiber Visualizer.
- Event Loss on the Pass/Fail Setup screen can be set for Reflective event and Non-Reflective event individually.

Function added and changed by upgrading the firmware version from 2.20 to 2.21.

- None

Function added and changed by upgrading the firmware version from 2.19 to 2.20.

- A folder to save measurement results can be selected for Automatic Saving function.
- A file name up to 21 characters can be set for Automatic Saving function.
(Up to 14 characters in Fiber Scope as before)
- Some foreign languages are available in Fiber Visualizer.
- A Bluetooth device can be recognized automatically when displaying a screen other than the Top menu.

Function added and changed by upgrading the firmware version from 2.18 to 2.19.

- None

Function added and changed by upgrading the firmware version from 2.17 to 2.18.

- Changed the fonts of Chinese(S).
- Changed SM PC>45 to SM UPC>45 in the VIP test profile.
- Changed the VIP report layout below.
 - Removed the individual tables of Probe Model, Tip Type, File Name, and Capture Time, and integrated them into VIP Test Information.
 - Removed Analysis Results from VIP Test Information and added a new table of Analysis Results.
- Changed the setting range of the Sequence Number in the following screen and tab. The new range is 0 to 9999. Also, changed its default value to 1.
 - The Setup-Auto Save screen (OTDR, Fiber Visualizer)
 - The Setup tab (VIP)

Function added and changed by upgrading the firmware version from 2.14 to 2.17.

- None

Function added and changed by upgrading the firmware version from 2.13 to 2.14.

- The Fiber Visualizer function has been added to the Top Menu screen.
The Fiber Visualizer function provides splice points and faults in a fiber using graphic icons, for easily locating events in the fiber.
- The threshold value for analyzing the splitter can be now set by the number of splits.
The threshold value is automatically set by selecting the number of splits.
- The threshold values for analysis and pass/fail evaluation can be now set from the pop-up menu.
For OTDR and Fiber Visualizer, the threshold values can be changed just by selecting **Analysis Setup** or **Pass/Fail Setup** in the pop-up menu.
- Inequality signs (>, <) are now not added to Reflectance and ORL calculation results that are less than the threshold values.

Function added and changed by upgrading the firmware version from 2.12 to 2.13.

- Made changes to the following defaults:
Auto Back light: 30 sec → 5 min
Auto Power Off: Off → 10 min

Function added and changed by upgrading the firmware version from 2.11 to 2.12.

- None

Function added and changed by upgrading the firmware version from 2.10 to 2.11.

- None

Function added and changed by upgrading the firmware version from 1.05 to 2.10.

- Pass/fail evaluation of optical fiber end face images has become available on the VIP screen.
End of an optical interconnect can be automatically inspected according to the IEC 61300-3-35 standard. Analysis results can be output in a report format, together with an image, to a PDF file.
- Remote control of the mainframe has become available from a control terminal.
For wireless connection, a USB Wi-Fi dongle is required on the mainframe. Also, for wired connection, a USB Ethernet converter is required.
- Folder sharing between control terminal and mainframe has become available.
You can also access the shared folders on the PC participating in the domain.
- It has become possible to send and receive files via Bluetooth.
Files can be sent, received, and deleted by accessing each other's shared folders from mainframe or control terminal.
- Macrobend detection has become available on the OTDR screen.
Macrobend event can be detected by dual-wavelength measurement (1310 nm and 1550 nm).
- Dual-wavelength measurement (1310 nm and 1550 nm) has become available on the OTDR screen.
Though the earlier versions required you to manually switch wavelengths, auto wavelength switching during measurement has become available.
- It has become possible to select fiber types you want to display on the OTDR screen when setting IOR.
You can display required fiber types only.
- The 2-pt Loss (LSA) mode has been added to the OTDR screen.
- Password protection of the mainframe has become available at startup.

Function added and changed by upgrading the firmware version from 1.04 to 1.05.

- None

Function added and changed by upgrading the firmware version from 1.03 to 1.04.

- Zero offset is now available at Power Meter screen.
Accurate value can be obtained by executing zero offset prior to power measurement.

5. Solved Software Issues

Model Name	Description
MU909814B/15B Ver. 4.04	➤ Improved the function relating to manufacturing inspection. It is not possible to downgrade to firmware prior to 4.02 when V4.04 was installed.
MU909814B/15B Ver. 4.02	➤ Fixed a display bug that occurred with some limited models. This bug occurred when V4.01 was installed.
MU909814B/15B Ver. 4.01	➤ Fixed a bug that files cannot be sent and received with the remote GUI.
MU909814B/15B Ver. 4.00	➤ Improved the function relating to manufacturing inspection.
MU909814B/15B Ver. 3.05	➤ Improved the function relating to manufacturing inspection.
MU909814B/15B Ver. 3.04	➤ None.
MU909814B/15B Ver. 3.03	<ul style="list-style-type: none"> ➤ Improved the measurement accuracy of PON splitter loss. ➤ Fixed a bug that connection loss at OTDR port could be incorrect. ➤ Improved event detection performance. ➤ Fixed a bug that caused a level reduction in very few OTDR trace.
MU909814B/15B Ver. 3.02	➤ Improved the function relating to manufacturing inspection.
MU909814B/15B Ver. 3.01	➤ Improved the function relating to manufacturing inspection.
MU909814B/15B Ver. 3.00	➤ Fixed a bug that Total Loss may not be calculated correctly.
MU909814B/15B Ver. 2.35	➤ The software was updated to display the measured value down to two digits after the decimal point on the power meter screen.
MU909814B/15B Ver. 2.34	➤ Fixed a bug that sometimes the measurement result could not be able to be saved in ZIP format.

Cont'd

Model Name	Description
MU909814B/15B Ver. 2.33	<ul style="list-style-type: none"> ➤ Fixed a bug that automatic setting was not executed correctly on OTDR or Fiber Visualizer. ➤ Fixed a bug that OTDR and Fiber Visualizer was not start when the unit's power is turned off automatically. ➤ Fixed a bug that the save destination of the trace data was the "/ Properties" folder when the unit's power is turned off automatically. ➤ Fixed a bug that battery warning was displayed in English when Japanese display was selected.
MU909814B/15B Ver. 2.32	<ul style="list-style-type: none"> ➤ Improved the function relating to manufacturing inspection. ➤
MU909814B/15B Ver. 2.31	<ul style="list-style-type: none"> ➤ Fixed a bug that sometimes unit cannot be saved correctly in ZIP format. ➤ Improved the function relating to manufacturing inspection. ➤
MU909814B/15B Ver. 2.30	<ul style="list-style-type: none"> ➤ Optimized a Full Auto setting of Fiber Visualizer. ➤ Fixed a bug that the unit is powered off when analyzing on VIP screen.
MU909814B/15B Ver. 2.29	<ul style="list-style-type: none"> ➤ Improved the function relating to manufacturing inspection.
MU909814B/15B Ver. 2.28	<ul style="list-style-type: none"> ➤ Fixed a bug in which the ORL pass/fail judgment was occasionally incorrect. ➤ Fixed a bug in which the splitter event was not judged pass/fail by OTDR occasionally. ➤ Fixed a bug in which the ORL value was occasionally miscalculated. ➤ Fixed a bug in which the total loss value was occasionally miscalculated. ➤ Optimized a method to calculate the dB/km loss.
MU909814B/15B Ver. 2.27	<ul style="list-style-type: none"> ➤ Fixed a bug that didn't save VIP settings when the unit was powered off.
MU909814B/15B Ver. 2.26	<ul style="list-style-type: none"> ➤ Fixed a bug that the controller firmware could no longer be updated after upgraded once by the V2.25 installer.
MU909814B/15B Ver. 2.25	<ul style="list-style-type: none"> ➤ Fixed a bug that Italian was not displayed correctly on the Trace Analysis screen. ➤ Fixed a bug that the Total Fiber Loss (Cum.Loss) was miscalculated occasionally when performing measurement with distance range of 10km or under, pulse width of 20ns or under, and resolution of less than 1m. ➤ Fixed a bug that the MT9090A could not be operated occasionally when went back to the top menu during measurement. ➤ Fixed a bug that the measurement result was not judged PASS occasionally even after the pass/fail threshold was changed. ➤ Fixed a bug that the fiber group was not initialized when performing All Defaults on the Test Setup screen.
MU909814B/15B Ver. 2.24	<ul style="list-style-type: none"> ➤ None.
MU909814B/15B Ver. 2.23	<ul style="list-style-type: none"> ➤ Fixed the bug that saving ZIP files had an error. ➤ Improved accuracy of detecting far-end events in OTDR measurement.

Cont'd

Model Name	Description
MU909814B/15B Ver. 2.22	<ul style="list-style-type: none"> ➤ Fixed the bug that the VFL icon was not displayed on the Setup screen. ➤ Fixed the bug that the dummy fiber was not displayed occasionally when measuring 2 wavelengths. ➤ Fixed the bug that the scroll icon on the right was disabled and the fiber line at the right end was not displayed when selecting the first among three events in Fiber Visualizer. ➤ Fixed the bug that the Summary screen did not appear occasionally even after changing Analysis setup and re-executing Analysis on the Trace View screen of Fiber Visualizer. ➤ Fixed the bug that the events that were actually under the Event Loss threshold on the Analysis Setup screen were detected occasionally. ➤ Distance display on the Events screen became more visible when Color Theme of Fiber Visualizer was set to Night.
MU909814B/15B Ver. 2.21	<ul style="list-style-type: none"> ➤ Fixed the bug that the screen is white when MT9090A is started by pressing the F1 key.
MU909814B/15B Ver. 2.20	<ul style="list-style-type: none"> ➤ Fixed the bug that NAN was displayed in the calculation results of all fiber losses. ➤ Fixed the bug that VFL could not be selected when measuring with 2 wavelengths. ➤ Changed the increment timing of the sequence start number that is set in the Automatic Saving screen. ➤ Fixed the bug that the indicator did not light up when the PDF Report Creation screen was displayed while the visible light source is On (blinking) on Fiber Visualizer. ➤ Fixed the bug that distance of an event different from the selected one is displayed when changing IOR/BSC by Fiber Visualizer. ➤ Fixed the bug that Fiber Visualizer kept showing the message "Calculation in progress". ➤ Corrected Spanish mistakes. ➤ Fixed the bug that F1 key is disabled when switching languages on the Connection Check screen.
MU909814B/15B Ver. 2.19	<ul style="list-style-type: none"> ➤ Fixed the bug that prevented Fiber Visualizer from performing measurement normally when Test Mode was set to Dual WL.
MU909814B/15B Ver. 2.18	<ul style="list-style-type: none"> ➤ Fixed a bug that the characters in PDF report were not output correctly in some languages such as Chinese-Traditional. ➤ Adjusted the size of the range circle for analysis of image captured by G0306A probe, in the VIP screen.
MU909814B/15B Ver. 2.17	<ul style="list-style-type: none"> ➤ Fixed a bug that the software shuts down after Anritsu logo appears at start-up in rare cases. ➤

Cont'd

Model Name	Description
MU909814B/15B Ver. 2.14	<ul style="list-style-type: none"> ➤ Fixed bug that caused this equipment to be connected to a different device when connecting via Bluetooth. ➤ Changed the location to store the password for the Wi-Fi access point so that the user cannot access it. ➤ Fixed bug that could not display an error message when saving an SOR file if there is not enough disk space. ➤ Fixed bug that made the processing load heavy when removing a network device. ➤ Fixed bug that could not normally save a VIP image on the VIP screen. ➤ Fixed bug that changed PASS/FAIL evaluation when switching the language mode from English to Japanese. ➤ Fixed bug that changed the threshold for pass/fail evaluation to an erroneous value when switching the language mode from Japanese to English.
MU909814B/15B Ver. 2.13	<ul style="list-style-type: none"> ➤ None.
MU909814B/15B Ver. 2.12	<ul style="list-style-type: none"> ➤ None.
MU909814B/15B Ver. 2.11	<ul style="list-style-type: none"> ➤ Fixed bug causing a power-down problem when Distance Range, Resolution or Pulse Width was selected on the OTDR screen.
MU909814B/15B Ver. 2.10	<ul style="list-style-type: none"> ➤ Fixed bug that could not switch the language of on-screen characters sometimes after switching the language. ➤ Fixed bug that could not sometimes write to a USB memory with more than 4 GB storage capacity. ➤ Fixed bug that could not correctly start the module sometimes when the battery power level was approximately 0.
MU909814B/15B Ver. 1.05	<ul style="list-style-type: none"> ➤ Fixed bug that zeroset is not completed with Standard Power Meter. ➤ Fixed bug that "Under Range" and "***.*" are switching with Standard Power Meter. ➤ Fixed bug that waveform file (.sor) cannot be saved when auto save function is enabled and a same file name is already in a saving folder.
MU909814B/15B Ver. 1.04	<ul style="list-style-type: none"> ➤ Fixed fluctuation of optical power when modulated light (270 Hz, 1 kHz, 2 kHz) is input at Power Meter screen.
MU909814B/15B Ver. 1.01	<ul style="list-style-type: none"> ➤ Fixed bug causing to unavailable to output current wave (CW) of VFL when using at Power Meter function.

6. Known Problems

Firmware version 4.04 for the MU909814/15 contains the following known problems:

Model Name	Description
MU909814B/15B	➤ None

7. Cautions

Read the following terms and conditions carefully before using the MU909814/15.

Model Name	Description
MU909814B/15B	<ul style="list-style-type: none"> ➤ Some commercially available USB memory may not be supported. Refer to Section 8. Upgrade Precautions for details of USB memory supported by Anritsu. ➤ BEFORE upgrading the firmware, ALWAYS read the MU909814B/15B Series Network Master Firmware Upgrade Procedure.

List of verified compatible USB device.

USB Ethernet Converter	
Planex	UE-100TX-G3
USB Wi-Fi dongle	
BUFFALO	WLI-UC-GNM
I-O DATA	WN-G300U
Logitec	LAN-W150N/U2
	LAN-W300N/U2
Sitecom	WL-329
	WL-345
	WLA-4000
USB Bluetooth dongle	
BUFFALO	BSHSBD04BK
	BSHSBD05BK
	BSHSBD08BK
IOGEAR	GBU421
Logitec	LBT-UAN01C1
Planex	BT-Micro3H2X
	BT-MicroEDR1X
Sanwa Supply	MM-BTUD27
Targus	ACB20EU
Technika	NBA111

8. Upgrade Precautions

Download the newest firmware from the following URL.

- <https://www.anritsu.com/zh-cn/test-measurement/support/downloads?model=MU909814B/15B>

- Anritsu has confirmed compatibility with USB memory from the makers listed in the following table. If your USB memory is not recognized by the MT9090A, please purchase one of the supported media types.

Manufacturer	Model/capacity
Sony	POCKET BIT/32MB
Sony	POCKET BIT 512MB Turbo
GREEN HOUSE	PicoDrive/64 MB
TOSHIBA	TransMemory/256 MB
TOSHIBA	TransMemory/512 MB
ADTEC	DATASTICK/64 MB
Princeton	X i a o Jr./64 MB
BUFFALO	RUF2 - E1G - B/512MB
I-O DATA	ToteBag/512MB
Scan Disk	Cruzer Micro with Skins USB Flash Drive/256MB
imation	Flash Drive Mini with swivel cap/256MB
Transcend	JetFlash / 256MB

- NEVER remove the USB memory inserted into the MT9090A while updating, otherwise the firmware update will fail, leaving the MT9090A unable to restart.
- When updating the firmware, do not press any key on the MT9090A, otherwise the firmware update may fail, leaving the MT9090A unable to restart.
- When updating the firmware, do not turn off the power to the MT9090A, otherwise the firmware update will fail, leaving the MT9090A unable to restart.
- When updating the firmware, do not remove the AC adapter plug from the MT9090A, otherwise the firmware update may fail, leaving the MT9090A unable to restart.

If the firmware update fails and the MT9090A cannot restart, please contact our Anritsu sales representative.