ANRITSU CORPORATION

MU909060A Family Release Note for Version 3.09

This Release Note covers the MU909060A family of products. This document contains the following Items.

envision : ensure **/Inritsu**

1. Manuals

Model No.	Operation Manual	Edition
M-W3166AE	Appendix B.2 Remote Control Removed description of Adobe Flash™ player installation.	17.0
M-W3166AW	As above (Japanese document)	19.0

2. Version Information

Model Name	Versions
MU909060A1/2/3	3.09

3. New Features and Enhancements

Feature	Description

4. Specification Changes and Bug Fixes

Model Name	Change
MU909060A1/2/3	Fixed bug causing incorrect calculation of UDP checksum when using UDP traffic at Y.1564 test
MU909060A1/2/3	Changed Remote GUI function to not use Adobe Flash—no change in Remote GUI function itself

5. Known Problems

Model Name	Known Bug Contents

6. Usage Notes

Refer to the operation manual for details about how to confirm the version information and other notes on use.

envision : ensure /Anritsu