

General Caution

If there is a Software update question, please contact Anritsu service support at <https://techsupport.anritsu.com>, and then click on "Technical Support" for further information.

What will the customer see in this release?

Product : MX281000A
Application Package : V2025.6.2
Release Date : Release May, 2026

*** IMPROVEMENTS ***

-> Software

- Improved handling of LMR Mode switch prevent rare out of sync errors.
- Improved abort handling ensuring Push-To-Talk is off.
- Improved a better alignment retry logic for Tx Attenuator, Tx Characterization Points, and Bit Error Rate.
- Improved a proper image being used for portable radios in the setup diagram.
- Added new Quick Start Guide to the User Guide under Help.

*** BUG FIXES ***

-> Software

- Fixed a rare Bug where Power Sensor needed to be restarted.
- Fixed an issue with doing a setup test immediately after Calibration.

What will the customer see in this release?

Product : MX281000A

Application Package : V2025.6.1

Release Date : Release July, 2025

-> Software

- MX281000A Initial Software Release.
