

General Caution

Please use a USB Memory Stick for firmware updates.

If there is a firmware update question, please contact Anritsu service support at <https://www.anritsu.com/test-measurement/contact-us> for further information.

What will the customer see in this release?

Product : S331P

Application Package : V2023.4.1

Release Date : Quarterly Release Sept. 2023

Information below may not apply to every model/option in Product list

*** IMPROVEMENTS ***

-> Software - S331P

[SNC-986] Added new fire rated cable AFW-2HFR-3 7/8 to the CableList.

[SNC-989] Updated and revised the End User License Agreement.

*** BUG FIXES ***

-> Software - S331P

[SNC-998] Fixes issue where an application error would occur when the Start Frequency was set beyond the Stop Frequency with Limits enabled.

What will the customer see in this release?

Product : S331P

Application Package: V2020.8.1

Release Date : Quarterly Release August, 2020

Information below may not apply to every model/option in Product list

*** NEW FEATURES ***

-> Software - S331P

[SNC-962] The following cables have been added per customer requests: RLCX-SL 158R; RLCX-SL 114R; RLCX-SL 078R; RLCX-SL012R; RLCX-SL038R; RLCX-SL014R; RLCX-SL012S; RLCX-SL038S; RLCX-SL014S; RLCX-SL012R FPR

*** BUG FIXES ***

-> Software - S331P

[SNC-968] Resolved an issue where some files could accidentally get permanently deleted if a failure occurred during a file copy/move operation from the internal memory to an external USB memory device.

[SNC-970] Fixes an issue where remote communications cannot be established on some Windows OS's (Windows 10 in particular). In the case of a failure to establish port 9001 as the communications port the application will automatically use port 59001 instead.