

ERRATA

Rev. 2.1 (1/1)

MP8931A Operation Manual

The following revisions were made after the second edition of the MP8931A Operation Manual was issued. Please read the column on the right for the changes to the items in the column on the left.

PAGE	FOR	READ
P. A-7	Appendix A Specifications (4) DVB-ASI Interface Level 800 mV (p-p) Line Rate 270 Mbaud	Level 800 mV (p-p) $\pm 10\%$ Line Rate 270 Mbaud ± 100 ppm